

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

*OTM/W 1318437317*

**OPERATOR**  Initial Report  Final Report

Name of Company Oxy Permian <i>16696</i>	Contact C.J. Summers
Address 102 S. Main St. Carlsbad, NM 88220	Telephone No. 575-397-8216
Facility Name SDS II Federal I SWD Battery	Facility Type SWD
Surface Owner BLM	Mineral Owner BLM
API No. 30-015-27627	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	11	24S	31E	2090	North	1980	West	Eddy

Latitude 32.23339 Longitude -103.75070

**NATURE OF RELEASE**

Type of Release Produced Water	Volume of Release 20 bbls	Volume Recovered 0 bbls
Source of Release Transfer Pump	Date and Hour of Occurrence May 13, 2013 Time: Unknown	Date and Hour of Discovery May 13, 2013 Time: Unknown
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos of the BLM and Mike Bratcher of NMOCD	
By Whom? C.J. Summers	Date and Hour 5/15/2013 @ 1:38 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

**RECEIVED**  
 JUN 26 2013  
**NMOCD ARTESIA**

If a Watercourse was Impacted. Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
 The release was due to a leak on the triplex transfer pump line. Initial remedial actions will be conducted by Oxy. Talon/LPE was contracted to perform an initial site assessment and soil sampling. Upon receipt of analytical results from the soil sampling activities a work plan will be drafted and remedial activities will begin upon its approval.

Describe Area Affected and Cleanup Action Taken.\*  
 The fluid from this release flowed north and west across the location. The fluid ran off of the Northern side of the location and flowed into the pasture for approximately 280-feet. Talon/LPE collected soil samples on the location as well as in the flow path running in the pasture.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: C.J. Summers	Approved by Environmental Specialist:	Signed By <i>Mike Bratcher</i>
Title: HES Advisor	Approval Date: <b>JUL 03 2013</b>	Expiration Date:
E-mail Address: Chancey_Summers@oxy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <i>6-30-13</i> Phone: 575-397-8216	Remediation per OCD Rule & Guidelines, & like approval by BLM. <b>SUBMIT REMEDIATION PROPOSAL NO LATER THAN:</b>	

*August 3<sup>rd</sup>, 2013*

*2RP-1704*

\* Attach Additional Sheets If Necessary

**From:** Chancey\_Summers@oxy.com  
**Sent:** Wednesday, May 15, 2013 1:38 PM  
**To:** dadkins@talonlpe.com; jamos@blm.gov; jvancure@blm.gov; Bratcher, Mike, EMNRD  
**Subject:** SDS 11 FEDERAL 1 SWD BATTERY

All this is to inform you Oxy Permian South had a leak on the SDS on May 13, 2013. Oxy released 20 bbls of produced water. None was recovered. The leak was due to a leak on the triplex transfer pump line. The location is located in Sect 11, Township 24S, Range 31E, of Eddy County. Oxy will conduct some initial remediation. C141 to follow. Driving directions. Off Hwy 128, turn South on Buck Jackson road go 1.5 mile, turn West 150 ft take right at Y go 2.5-3 miles, 1st lease to the right. Let me know if you have any questions.

Thank You  
C.J. Summers  
HES Advisor  
Cell # 575-631-9436  
Office # 575-397-8216  
[Chancey\\_Summers@oxy.com](mailto:Chancey_Summers@oxy.com)

"When the blind lead the blind, get out of the way!"

**Warren, JeanMarie, EMNRD**

---

**From:** Warren, JeanMarie, EMNRD  
**Sent:** Tuesday, June 18, 2013 10:31 AM  
**To:** Chancey\_summers@oxy.com  
**Cc:** Bratcher, Mike, EMNRD  
**Subject:** SDS 11Fed 1SWD Btry

Good Morning CJ.

I was wondering if you have submitted a C-141 on file for this well/btry. We don't seem to have a record of the release on file as far as a C-141. We have only the email of the notification.

The release date was 5/13/2013 of 20bbbls PW. None was recovered. API # 30-015-27627

Sec 11-T24S-R31E

Please let us know when you can get that to us as it has already been over 1 month since we received the email notification.

*Jean-Marie Warren  
Business Operations Specialist  
NM-OCD, Artesia  
District II  
811 S. First St.  
Artesia, NM 88210  
(575) 748-1283 ext. 101*

6/26/13 8:05AM Called CS Summers on his Cel  
Phone # 575-631-9436. He stated he signed the  
C-141 last week and we should have it already.  
He stated he would call Talon the company  
he is using to see where it is.