


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003  
Submit 3 Copies to appropriate Office in accordance with Rule 116 on back side of form

**Release Notification and Corrective Action**

*nJMW 1318452944*

OPERATOR  Initial Report  Final Report

Name of Company	COG OPERATING LLC <i>229137</i>	Contact	Pat Ellis
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	GEHRIG FEDERAL COM #005H	Facility Type	TANK BATTERY

Surface Owner	FEDERAL	Mineral Owner		Lease No. (API#)	30-015-37678
---------------	---------	---------------	--	------------------	--------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	09	26S	29E					EDDY

Latitude 32.05086 Longitude 103.98149

**NATURE OF RELEASE**

Type of Release	Produced water	Volume of Release	20bbls	Volume Recovered	19bbls
Source of Release	3" line	Date and Hour of Occurrence	06-16-2013	Date and Hour of Discovery	06-16-2013 5:00pm
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
A 3" line failed going from the heater treater to the produced water tank. The line has been replaced to prevent any reoccurrences.

Describe Area Affected and Cleanup Action Taken.\*  
Initially 20bbls of produced water were released due to a 3" line from the heater treater to the produced water tank. We were able to recover 19bbls of produced water with a vacuum truck. The spill was completely contained inside the lined facility walls. All free fluid has been recovered. Any contaminated gravel has been removed, the liner has been steam cleaned, and we have replaced with fresh gravel as necessary. This facility has been returned to its prior condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<i>Robert Grubbs Jr.</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name:	Robert Grubbs Jr.	Approved by District Supervisor:	Signed By <i>Mike Brannon</i>
Title:	Senior Environmental Coordinator	Approval Date:	JUL 03 2013
E-mail Address:	rgrubbs@concho.com	Expiration Date:	
Date:	06-28-2013	Phone:	432-661-6601


Conditions of Approval:  
**Like approval by BLM**  
Attached   
*2RP-1708*

\* Attach Additional Sheets If Necessary

**Bratcher, Mike, EMNRD**

---

**From:** Robert Grubbs <RGrubbs@concho.com>  
**Sent:** Friday, June 28, 2013 2:38 PM  
**To:** Amos, James <jamos@blm.gov> (jamos@blm.gov); Bratcher, Mike, EMNRD  
**Cc:** Joshua Russo  
**Subject:** C-141 Initial/Final Report - Gehrig Federal Com #005H (Tank Battery)  
**Attachments:** GEHRIG FEDERAL COM #005H (TANK BATTERY) -- DATE OF RELEASE -- 06-16-2013.pdf



Gentlemen,

Please see attached the C-141 Initial / Final Report for a release that occurred at our Gehrig Federal Com #005H (Tank Battery) on 06-016-2013. This is a lined facility.

Thank you,

*Robert Grubbs Jr.*  
*Sr. Environmental Coordinator*  
432.683.7443 (main)  
432.818.2369 (direct)  
432.661.6601 (cell)  
[rgrubbs@concho.com](mailto:rgrubbs@concho.com)

*Mailing Address:*  
*One Concho Center*  
*600 W. Illinois Avenue*  
*Midland, Texas 79701*



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.