

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nTJW/1319637807

Initial Report Final Report

Name of Company Yates Petroleum Corporation		OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 TH Street		Telephone No. 575-748-1471	
Facility Name Louise AYL #2	API Number 30-015-33938	Facility Type Battery	
Surface Owner Fee	Mineral Owner Fee	Lease No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	25	21S	26E	990	North	1550	East	Eddy

Latitude 32.45514 Longitude 104.24217


NATURE OF RELEASE

Type of Release Produced water mixed with fresh water	Volume of Release 48 B/PW	Volume Recovered 130 B/PW and B/FW Mix
Source of Release Produced water tank	Date and Hour of Occurrence 6/20/2013; PM	Date and Hour of Discovery 6/20/2013; PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/NMOCD II	
By Whom? Robert Asher/Yates Petroleum Corporation	Date and Hour 6/21/2013; AM	NMOCD ARTESIA
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	JUL 05 2013
If a Watercourse was Impacted, Describe Fully.* N/A	RECEIVED	

Describe Cause of Problem and Remedial Action Taken.*
Lightning struck fiberglass produced water tank. Emergency equipment called to put out fire. Vacuum trucks called.

Describe Area Affected and Cleanup Action Taken.*
An approximate area of 20' X 40' (inside lined/bermed battery), approximate area of 15' X 25' (outside of battery), and area affected caused by lined battery being filled with fresh water to extinguish fire and overflowed (unknown amounts of PW/FW mix). Liner integrity intact. Vertical and horizontal delineation samples outside of battery will be taken and analysis ran for TPH & BTEX (chlorides for documentation). If initial analytical results for TPH & BTEX are under RRAL's a Final Report, C-141 will be submitted to the OCD requesting closure. If the analytical results are above the RRAL a work plan will be submitted to the OCD. **Depth to Ground Water: <50' (40', Section 25, T21S-R26E, of the NMOSE), Wellhead Protection Area: No, Distance to Surface Water Body: > 1000', SITE RANKING IS 20.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:  Printed Name: Robert Asher Title: NM Environmental Regulatory Supervisor E-mail Address: boba@yatespetroleum.com Date: Friday, July 05, 2013 Phone: 575-748-4021	OIL CONSERVATION DIVISION Approved by District Supervisor: Signed By:  Approval Date: JUL 15 2013 Expiration Date: Conditions of Approval: Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN: Attached <input type="checkbox"/>
--	--

* Attach Additional Sheets If Necessary

August 15, 2013

ZRP-1718



FACSIMILE TRANSMITTAL SHEET

FROM:
Robert Asher**TO:**
Mike Bratcher/NMOCD II**DATE:**
Friday, July 05, 2013**FAX NUMBER:**
9-748-9720**TOTAL NO. OF PAGES INCLUDING COVER:**
2**RE:**
C-141; Louise AYI #2**NOTES:****COMMENTS:**

URGENT FOR REVIEW PLEASE COMMENT PLEASE REPLY PLEASE RECYCLE

NOTES/COMMENTS:**INITIAL REPORT.**

This report is for a 6/20/2013 release.

If you have any questions, contact me at 575-748-4217.

Thank you.

Robert Asher

Environmental Regulatory Department

Bratcher, Mike, EMNRD

From: Bob Asher <BobA@yatespetroleum.com>
Sent: Friday, June 21, 2013 8:03 AM
To: Bratcher, Mike, EMNRD; Dade, Randy, EMNRD
Cc: Amanda Trujillo; Amber Cannon; Katie Parker; Lupe Carrasco
Subject: Release (Louise AYI #2)

Yates Petroleum Corporation is reporting a release at the following location (6/21/2013).

Louise AYI #2
30-015-33938
Section 25, T21S-R26E
Eddy County, New Mexico

Released: Unknown amounts of Produced Water; Recovered: Not known at this time

Lightning struck fiberglass tank. Emergency units called to control/put out fire. Vacuum truck(s) were called to recover water and crews called to dismantle batter. No further information at this time.

A Form C-141 Initial Report will be submitted with complete information.

Thank you.

Robert Asher
NM Environmental Regulatory Supervisor
Yates Petroleum Corporation
105 S. 4th Street
Artesia, NM 88210
575-748-4217 (Office)
575-365-4021 (Cell)

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.
