


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

JMW1319653044 OPERATOR Initial Report Final Report

Name of Company	COG OPERATING LLC <i>229137</i>	Contact	Pat Ellis
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	CLUSTER STATE COM #001H	Facility Type	TANK BATTERY
Surface Owner	STATE	Mineral Owner	Lease No. (API#) 30-015-37547

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	16	26S	27E					EDDY

Latitude 32.04866 Longitude 104.20266

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	80bbbs	Volume Recovered	79bbbs
Source of Release	Oil tank	Date and Hour of Occurrence	07-06-2013	Date and Hour of Discovery	07-06-2013 10:00am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher - NMOCD		
By Whom?	Michelle Mullins	Date and Hour	07-08-2013 8:17am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Oil was turned in and expected to be hauled off. The haul truck only hauled off two loads when eight was needed. Follow up with the trucking company to make sure that the proper amounts of fluids have been hauled off.

Describe Area Affected and Cleanup Action Taken.*
Initially 80bbbs were released from an overflowing oil tank we were able to recover 79bbbs with a vacuum truck. The release was contained inside the lined facility. All free fluid has been recovered. Contaminated gravel has been removed from the facility and has been replaced with fresh gravel. The facility has been returned to its prior condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.


Signature: <i>Robert Grubbs Jr.</i>		OIL CONSERVATION DIVISION	
Printed Name: Robert Grubbs Jr.	Title: Senior Environmental Coordinator	Approved by District Supervisor: <i>Mike Bratcher</i>	Signed By: <i>Mike Bratcher</i>
E-mail Address: rgrubbs@concho.com	Date: 07-09-2013	Approval Date: JUL 15 2013	Expiration Date:
Phone: 432-661-6601	Conditions of Approval:		Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

2RP-1720

Bratcher, Mike, EMNRD

From: Robert Grubbs <RGrubbs@concho.com>
Sent: Tuesday, July 09, 2013 7:44 AM
To: Bratcher, Mike, EMNRD
Cc: Joshua Russo
Subject: C-141 Initial/Final Report - Cluster State Com #001H (Tank Battery)
Attachments: Cluster State Com #001H (Tank Battery) -- Date Of Release -- 07-06-2013.pdf



Mr. Bratcher,

Please see attached the C-141 Initial/Final Report for a release that occurred on 07-6-2013 at our Cluster State Com #001H (Tank Battery) in Eddy County New Mexico. This is a lined facility.

Thank you,

Robert Grubbs Jr.
Sr. Environmental Coordinator
432.683.7443 (main)
432.818.2369 (direct)
432.661.6601 (cell)
rgrubbs@concho.com
Mailing Address:
One Concho Center
600 W. Illinois Avenue
Midland, Texas 79701



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

Bratcher, Mike, EMNRD

From: Michelle Mullins <MMullins@concho.com>
Sent: Monday, July 08, 2013 7:17 AM
To: Bratcher, Mike, EMNRD
Cc: Joshua Russo; Robert Grubbs
Subject: Cluster State Com #1H-Immediate Notification

Mr. Bratcher:

At approximately 10:00 a.m. on 7/06/2013, a produced fluid release was discovered at the above-referenced facility. The fluid was contained inside the battery which is lined with 40 mil plastic. An estimated 80 barrels of produced fluid was released. The cause of the release is currently under investigation. We will follow up within 15 days with a C-141 Report. GPS coordinates, legal description and driving directions are below.

32.04867 104.20266

Cluster State Com #1H
Sec 16 T26S R27E
380' FNL & 330' FWL
Eddy County, NM
API 30-015-37547

From Highway 285, travel south to mile marker 5 (White's City Road). Turn west and travel approximately 7.8 miles. Turn south (one mile west of Road Runner Road) and travel approximately 1 mile. Battery is the first location on the right.

Michelle Mullins
HSE Field Technician
COG Operating, LLC
(432) 934-1052
mmullins@concho.com

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.