



District I
1625 N. French Dr., Hobbs, NM 88240
District II
511 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011
Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

JMW 1319134649 OPERATOR Initial Report Final Report

Name of Company: Mewbourne Oil Company 14744	Contact: Zack Thomas
Address: PO Box 5270 Hobbs, NM, 88241	Telephone No. (575) 602-2188
Facility Name: Delaware Ranch SWD	Facility Type: Disposal
Surface Owner: Private	Mineral Owner: N/A
API No. 30-015-22734	

LOCATION OF RELEASE

Unit Letter	Section II	Township 26S	Range 28E	Feet from the 660	North/South Line South	Feet from the 660	East/West Line East	County Eddy
-------------	------------	--------------	-----------	-------------------	------------------------	-------------------	---------------------	-------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release: Overflow	Volume of Release: 50 bbls	Volume Recovered: 0 bbls
Source of Release: Tank thief hatch	Date and Hour of Occurrence: 7-3-13	Date and Hour of Discovery: 7-3-13
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? George Brantley	
By Whom? Zack Thomas	Date and Hour: 7-5-13	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse:	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

SWD Pump did not kick on automatically therefore tanks were ran over. When pumper arrived on location he immediately started swd pump which stopped the leak.

Describe Area Affected and Cleanup Action Taken.*

Leak contaminated a 150 ft by 25 ft area west of the tank containment. All fluids stayed on the pad. Contaminated soil will be excavated and hauled to Leal and.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health of the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Zack Thomas</i>	OIL CONSERVATION DIVISION	
Printed Name: Zack Thomas	Approved by Environmental Specialist:	Signed By: <i>Mike Brantley</i>
Title: Environmental Rep	Approval Date: 1 6 2013	Expiration Date:
E-mail Address: zthomas@mewbourne.com	Conditions approved: JUL 16 2013	Attached <input type="checkbox"/>
Date: 6-19-13	Phone: (575) 602-2188	

* Attach Additional Sheets If Necessary

Remediation per OCD Rule & Guidelines. **SUBMIT REMEDIATION PROPOSAL NO LATER THAN:**

August 16, 2013

2RP-1723

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: Mewbourne Oil Company	Contact: Zack Thomas
Address: PO Box 5270 Hobbs, NM, 88241	Telephone No. (575) 602-2188
Facility Name: Delaware Ranch SWD	Facility Type: Disposal

Surface Owner: Private	Mineral Owner: N/A	API No. 30-015-22734
------------------------	--------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	11	26S	28E	660	South	660	East	Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release: Overflow	Volume of Release: 50 bbls	Volume Recovered: 0 bbls
Source of Release: Tank thief hatch	Date and Hour of Occurrence: 7-3-13	Date and Hour of Discovery: 7-3-13
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? George Brantley	
By Whom? Zack Thomas	Date and Hour: 7-5-13	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

SWD Pump did not kick on automatically therefore tanks were ran over. When pumper arrived on location he immediately started swd pump which stoppped the leak.

Describe Area Affected and Cleanup Action Taken.*

Leak contaminated a 150 ft by 25 ft area west of the tank containment. All fluids stayed on the pad. Contaminated soil will be excavated and hauled to Leal and.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Zack Thomas</i>	OIL CONSERVATION DIVISION	
Printed Name: Zack Thomas	Approved by Environmental Specialist:	
Title: Environmental Rep	Approval Date:	Expiration Date:
E-mail Address: zthomas@mewbourne.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 6-19-13	Phone: (575) 602-2188	

* Attach Additional Sheets If Necessary

Warren, JeanMarie, EMNRD

From: Bratcher, Mike, EMNRD
Sent: Thursday, July 11, 2013 7:57 AM
To: Warren, JeanMarie, EMNRD
Subject: FW: Delaware SWD c141
Attachments: Delaware SWD C141 scan.pdf

-----Original Message-----

From: Zack Thomas [<mailto:zthomas@mewbourne.com>]
Sent: Wednesday, July 10, 2013 8:56 AM
To: Bratcher, Mike, EMNRD
Subject: Delaware SWD c141

(See attached file: Delaware SWD C141 scan.pdf)

⑤

Bratcher, Mike, EMNRD

From: Zack Thomas <zthomas@mewbourne.com>
Sent: Friday, July 05, 2013 2:37 PM
To: Bratcher, Mike, EMNRD
Subject: Delaware disposal

Mike,
We had a leak at the delaware disposal off of longhorn road on 285, just wanted to notify you. Spill report will be submitted monday.
Thanks
Zack
Sent from my iPhone