


District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources



Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Release Notification and Corrective Action

njm 1319931142

OPERATOR

Initial Report Final Report

Name of Company: BOPCO, L.P. <i>260737</i>	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: Hudson Federal Battery #1 On Pad with Hudson Federal well #7	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-31513
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter F	Section I	Township 23S	Range 30E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude N 32.336050 Longitude W 103.836788

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release: 15 bbls	Volume Recovered: 8 bbls
Source of Release: Water transfer pump	Date and Hour of Occurrence 5/17/13 time unknown	Date and Hour of Discovery 5/17/13 9:00 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
A 1/4" plug vibrated out of a water transfer pump causing water to spill inside of the 0 perm containment and sprayed outside on the ground. The plug was replaced.

Describe Area Affected and Cleanup Action Taken.*
Approximately 1800 sq. ft of tank battery pad and approximately 400 sq. ft. of pasture. The free standing fluid was recovered. The spill area will be remediated according to the NMOCD and BLM remediation guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Approved by Environmental Specialist	Signed By: <i>Mike Brannon</i>
Title: Waste Management and Remediation Specialist	Approval Date: JUL 18 2013	Expiration Date:
E-mail Address: <i>tasavoie@basspet.com</i>	Conditions of Approval: Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	
Date: 7/14/13	Phone: 432-556-8730	Attached <input type="checkbox"/>

August 18, 2013 *2RP-1732*

* Attach Additional Sheets If Necessary