

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nMLB 13108 29726

OPERATOR

Initial Report Final Report

Name of Company: <i>Legend Natural Gas 258894</i>	Contact: <i>Kody Phillips</i>
Address: <i>15021 Katy Freeway, Ste 200, Houston, TX 77094</i>	Telephone No.: <i>575-520-0747</i>
Facility Name: <i>Pipeline Right-of-way</i>	Facility Type: <i>Pipeline</i>

Surface Owner: <i>Pardue Limited Company</i>	Mineral Owner: <i>NA</i>	API No.: <i>NA</i>
--	--------------------------	--------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	<i>28</i>	<i>24S</i>	<i>28E</i>					<i>Eddy</i>

Latitude *32.1921* Longitude *-104.0973*


NATURE OF RELEASE

Type of Release: <i>Produced water</i>	Volume of Release: <i>25 bbls</i>	Volume Recovered: <i>see cleanup below</i>
Source of Release: <i>4-inch pipeline</i>	Date and Hour of Occurrence: <i>14:00, April 9th, 2013</i>	Date and Hour of Discovery: <i>14:30, April 9th, 2013</i>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
A watercourse was not reached.

Describe Cause of Problem and Remedial Action Taken.*
Leak at seam of 4" poly pipeline, pipeline crew was called immediately and line was repaired.

Describe Area Affected and Cleanup Action Taken.*
Produced water pooled in a low spot, standing water was recovered. Affected/moist soil was removed immediately with a backhoe and dump truck and hauled to Controlled Recovery Inc. for disposal on April 9th, 2013.



I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Matt Henderson</i>	OIL CONSERVATION DIVISION	
Printed Name: <i>Matt Henderson</i>	Approved by Environmental Specialist:	
Title: <i>Environmental Coordinator</i>	Approval Date:	Expiration Date:
E-mail Address: <i>mhenderson@lng2.com</i>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <i>April 15, 2013</i> Phone: <i>281-644-5950</i>		

* Attach Additional Sheets If Necessary

nMLB 13108 29345
MLB 13108 30455

2RP-1626