


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

OPERATOR Initial Report Final Report

Name of Company Enterprise Field Services LLC **Contact** Jim Heap
PO Box 4324, Houston, TX 77252 **Telephone No.** 432-686-5404

Facility Name Pipeline ROW, B6 Lateral **Facility Type:** Gas Gathering Pipeline

Surface Owner Multiple Owners **Mineral Owner** NA **Lease No.** NA

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	15	20S	25E					Eddy

Latitude 32.522478 N **Longitude** -104.396690 W

NATURE OF RELEASE

Type of Release Natural Gas	Volume of Release 2,470 MCF	Volume Recovered 0
Source of Release Pipeline Blow-down for Repair	Date and Hour of Occurrence 10-18-2012 09:00 hrs (MDT)	Date and Hour of Discovery 10-18-2012 09:00 hrs (MDT)
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher via Telephone	
By Whom? Jim Heap	Date and Hour 10-18-2012 11:30 hrs (MDT)	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
The pipeline was evacuated to atmosphere to complete repair of a previously reported leak.

Describe Area Affected and Cleanup Action Taken.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Matthew E. Marra	Accepted for record NMOCD	
Title: Senior Director, Environmental	Approval Date: JUL 31 2013	Expiration Date:
E-mail Address: memarra@eprod.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: Phone: 713-381-6684		

* Attach Additional Sheets If Necessary

fJMW 1321853859


iJMW 1321854250

2RP-1792



ENTERPRISE PRODUCTS PARTNERS L.P.
ENTERPRISE PRODUCTS HOLDINGS LLC
(General Partner)

ENTERPRISE PRODUCTS OPERATING LLC



October 18, 2012

7011 3500 0003 1118 1499
Return Receipt Requested

Mr. Mike Bratcher
New Mexico Oil Conservation Division
District 2 Office
811 South First Street
Artesia, New Mexico 88210

**RE: Form C-141 Report for Enterprise Products
B6 Lateral Line Blow-down**

Mr. Bratcher:

Enclosed, please find the requisite C-141 Form for the pipeline blow-down on our B6 Lateral on October 18, 2012.

This is sent pursuant to 29 (19.15.29) NMAC and as follow-up to verbal notification to you on October 18, 2012 by Jim Heap.

If you have any questions or need more information, please contact Jim Heap by phone at 432-686-5404, by email at jkheap@eprod.com or me at 713-318-6684

Regards,

Matthew E. Marra,
Senior Director, Environmental

/sjn
attachments