


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

NJMN 1322830932

OPERATOR

Initial Report Final Report

| | | | |
|-----------------|---|---------------|----------------|
| Name of Company | COG OPERATING LLC <i>229137</i> | Contact | Pat Ellis |
| Address | 600 West Illinois Avenue, Midland, TX 79701 | Telephone No. | 432-230-0077 |
| Facility Name | Burch Kelly Unit #205 | Facility Type | Injection Line |

| | | | | | |
|---------------|---------|---------------|--|------------------|--------------|
| Surface Owner | Federal | Mineral Owner | | Lease No. (API#) | 30-015-03133 |
|---------------|---------|---------------|--|------------------|--------------|

LOCATION OF RELEASE

| | | | | | | | | |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
| O | 26 | 17S | 29E | | | | | Eddy |

Latitude 32.80008 Longitude 104.04331

NATURE OF RELEASE

| | | | | | |
|-----------------------------|--|---|------------|----------------------------|--------------------|
| Type of Release | Produced water | Volume of Release | 10bbbls | Volume Recovered | 8bbbls |
| Source of Release | Injection line | Date and Hour of Occurrence | 08-01-2013 | Date and Hour of Discovery | 08-01-2013 11:00am |
| Was Immediate Notice Given? | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required | If YES, To Whom? | | | |
| By Whom? | | Date and Hour | | | |
| Was a Watercourse Reached? | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | | | |

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A ditcher hit a buried fiberglass injection line. The line has been repaired and back in service.

Describe Area Affected and Cleanup Action Taken.*

Initially 10bbbls of produced water were released from a fiberglass injection line that was struck by a ditcher. We were able to recover 8bbbls of produced water with a vacuum truck. All free fluids have been removed. A work plan will presented to the NMOCD/BLM for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.


| | | | |
|---|--|--|--------------------------------|
| Signature: <i>Robert Grubbs Jr.</i> | | OIL CONSERVATION DIVISION | |
| Printed Name: Robert Grubbs Jr. | | Approved by District Supervisor | Signed By <i>M. L. Brannon</i> |
| Title: Senior Environmental Coordinator | | Approval Date: AUG 16 2013 | Expiration Date: |
| E-mail Address: rgrubbs@concho.com | | Conditions of Approval: Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION PROPOSAL NO LATER THAN: | |
| Date: 8-13-2013 Phone: 432-661-6601 | | Attached <input type="checkbox"/> | |

* Attach Additional Sheets If Necessary

September 16, 2013 **2RP-1834**

Bratcher, Mike, EMNRD

From: Robert Grubbs <RGrubbs@concho.com>
Sent: Tuesday, August 13, 2013 4:16 PM
To: Bratcher, Mike, EMNRD; Amos, James <jamos@blm.gov> (jamos@blm.gov)
Cc: Robert McNeill; Tavarez, Ike; Kujawski, Marcus (Marcus.Kujawski@tetrattech.com)
Subject: C-141 Initial Report - Arabian 6 Fee #003H and the Burch Keely Unit #205
Attachments: Arabian 6 Fee #001 (Tank Battery) -- Date Of Release -- 08-01-2013.pdf; Burch Keely Unit #205 (Injection Line) -- Date Of Release -- 08-01-2013.pdf



Gentlemen,

Please see attached the C-141 Initial for a release that occurred at our Arabian 6 Fee #003H on 07-31-2013 and the Burch Kelly Unit #205 on 08-01-2013 in Eddy County New Mexico. We plan to assess the spill area timely.

Thank you,

Robert Grubbs Jr.
Sr. Environmental Coordinator
432.683.7443 (main)
432.818.2369 (direct)
432.661.6601 (cell)
rgrubbs@concho.com
Mailing Address:
One Concho Center
600 W. Illinois Avenue
Midland, Texas 79701



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.