



District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

*NTM* / *323842700*

**OPERATOR**  Initial Report  Final Report

Name of Company	Primero Operating, Inc. <i>18100</i>	Contact	Phelps White
Address	P.O. Box 1433, Roswell, NM 88202	Telephone No.	(575) 626-7660
Facility Name	Milano State # 001	Facility Type	Tank Battery

Surface Owner	State of NM	Mineral Owner	Fee	API No.	30-015-27614
---------------	-------------	---------------	-----	---------	--------------

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	36	24S	28E	2110	North	890	East	Eddy

Latitude N 32.17471° Longitude W 104.03485°

### NATURE OF RELEASE

Type of Release	Oil	Volume of Release	Unknown	Volume Recovered	None
Source of Release	Oil Tank	Date and Hour of Occurrence	Unknown	Date and Hour of Discovery	11/04/09
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
The oil tank at the battery leaked and a Letter of Violation was written on 11/04/09. No action has been taken.

Describe Area Affected and Cleanup Action Taken.\*  
The oil tank leaked inside the firewall of the tank battery. Visibly impacted soil will be excavated and disposed at an NMOCD approved disposal facility. Soil samples will be collected and analyzed for TPH, BTEX and chlorides in order to determine the extent of excavation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Phelps White	Approved by Environmental Specialist By:	
Title: President	Approval Date: <b>AUG 26 2013</b>	Expiration Date:
E-mail Address: pwiv@zianct.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 8/21/13 Phone: (575) 626-7660	Remediation per OCD Rule & Guidelines. <b>SUBMIT REMEDIATION PROPOSAL NO LATER THAN:</b>	

\* Attach Additional Sheets If Necessary

*Sept. 26, 2013*

*2RP-1867*

**Bratcher, Mike, EMNRD**

---

**From:** Cindy Crain <cindy.crain@gmail.com>  
**Sent:** Thursday, August 22, 2013 1:34 PM  
**To:** Bratcher, Mike, EMNRD  
**Cc:** Phelps White  
**Subject:** Primero Operating, Inc. - Milano State #1 - Initial C141  
**Attachments:** Initial C141.pdf

Mike,

Attached please find an initial C141 for the Primero Operating, Inc., Milano #1 Tank Battery. The site is located in Unit Letter H, Sec. 36, T24S, R28E, Eddy County, NM.

If you would please email a signed copy back to me, I would appreciate it.

Initial samples will be collected from the tank battery area next Wednesday, August 28, 2013. Once analytical results are received from the laboratory, I will prepare a remediation workplan for your review and approval.

Thank you,  
Cindy Crain

--  
*Crain Environmental*  
*(575) 441-7244*