


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Release Notification and Corrective Action

TJM
1323949781

OPERATOR Initial Report Final Report

Name of Company: Linn Operating <i>269324</i>	Contact: Brian Wall
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No.: 575-738-1739
Facility Name: Turner A # 45	Facility Type: Oil Producer
Surface Owner: Federal	Mineral Owner:
API No.: 3001528890	

LOCATION OF RELEASE

Unit Letter C	Section 19	Township 17S	Range 31E	Feet from the 975	North/South Line North	Feet from the 1450	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude: 32.8245844236141 Longitude: -103.912171012009

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 12 bbls	Volume Recovered: 2bbls
Source of Release: Steel 3" valve	Date and Hour of Occurrence: 08/25/2013 10:45am	Date and Hour of Discovery: 08/25/2013 10:45am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher- NM OCD Mike Burton-BLM	
By Whom? Brian Wall	Date and Hour 08/26/2013	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*:

Describe Cause of Problem and Remedial Action Taken.*: I came to Turner A#45, about 10:45 am, noticed a mess on the ground. I estimate 12 bbl. produced water. No oil. It was spread out on our location and Apache Tony #39. I inspected the leak, and found the 3 inch valve, on flowline, at wellhead had a hole in bottom of valve. I shut all valves at well. Then shut the valve at the header. Called Joe Hernandez and reported the spill. Had Lamina trucking suck up the free water, had Diversified change the 3 inch valve.

Describe Area Affected and Cleanup Action Taken.* : Estimate 200x25 ft. radius of spill. Estimate 2 bbl. water recovered. After repairs I opened all valves and put well back into production.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <i>Brian Wall</i>	Approved by District Supervisor: <i>Mike Bratcher</i>	
Printed Name: Brian Wall	Approval Date: AUG 27 2013	Expiration Date:
Title: Construction Foreman II	Conditions of Approval: Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	
E-mail Address: bwall@linenergy.com	Attached <input type="checkbox"/>	
Date: 08/26/2013 Phone: 806-367-0645		


* Attach Additional Sheets If Necessary

SEPTEMBER 27, 2013

2RP-1873

Bratcher, Mike, EMNRD

From: McCracken, Theresa <TMcCracken@linnenergy.com>
Sent: Monday, August 26, 2013 12:07 PM
To: mburton@blm.gov; Bratcher, Mike, EMNRD
Cc: Fitzwater, Nancy; Callahan, Terry; Moreno, Laura; Butters, Thomas; Golding, Chris; Wall, Fred
Subject: Linn- Turner A #45 8-25-13
Attachments: Turner A # 45 8-25-13.pdf



Please find attached the initial C-141 for the above referenced location.

Thank you,



Theresa McCracken

Field Administrator
LINN Energy, LLC
2130 W Bender
Hobbs, NM 88240
T: 575-738-1739 / F: 575-738-1740
tmccracken@linnenergy.com

This electronic message, together with any attachments, contains information from LINN Energy that may be confidential and intended solely for the use of the addressee only. If you are not the intended recipient, please note that any disclosure, dissemination, distribution or copying of this message, or any attachment, is strictly prohibited. Also, please notify the original sender by return e-mail and delete the message, along with any attachments, from your computer. Finally, the recipient should check this email and any attachments for the presence of viruses. The organization accepts no liability for any damage caused by any virus transmitted by this email.