

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

SEP 18 2013

Form C-141
Revised October 10, 2003

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC
RECEIVED

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: Linn Operating	Contact: Brian Wall
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No.: 575-738-1739
Facility Name: Government N # 2	Facility Type: Oil

Surface Owner: Federal	Mineral Owner:	API No.: 3002523122
------------------------	----------------	---------------------

LOCATION OF RELEASE

Unit Letter N	Section 19	Township 20S	Range 34E	Feet from the 590	North/South Line South	Feet from the 1913	East/West Line West	County Lea
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	---------------

Latitude: 32.552971798298 Longitude: -103.601948239229

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 40 bbls	Volume Recovered: 30 bbls
Source of Release: Heater	Date and Hour of Occurrence: 09/14/2013 9am	Date and Hour of Discovery: 09/14/2013 9am
Was Immediate Notice Given? NOT WITHIN 24 HRS gwl <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mark Whitaker- NM OCD Mike Burton- BLM	
By Whom? Brian Wall 9/18/13	Date and Hour 09/16/2013 8:45am 09/14/2013	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*:
GW @ 155'

Describe Cause of Problem and Remedial Action Taken.*: Casing valve at the well head was closed, heater lost all gas and everything from the vessel went to the water tank. The tank over filled.

Describe Area Affected and Cleanup Action Taken.*: Used vacuum truck to pickup oil from containment and backhole, crew

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Brian Wall	Jeffrey Seking Environmental Specialist	
Title: Construction Foreman II	Approval Date: 09/18/13	Expiration Date: 11/18/13
E-mail Address: bwall@linenergy.com	Conditions of Approval: DELINEATE AND REMEDIATE TO OCD REGS.	Attached <input type="checkbox"/>
Date: 09/16/2013 Phone: 806-367-0645	IRP-9-13-2954	

* Attach Additional Sheets If Necessary

SUBMIT FINAL C-141 BY 11/13/13

SEP 18 2013