

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

JMW 132553786 OPERATOR Initial Report Final Report

Name of Company Oxy Permian <i>16696</i>	Contact Chris Jones
Address 102 S. Main St. Carlsbad, NM 88220	Telephone No. 575-628-4121
Facility Name McCall 2 Battery	Facility Type Tank Battery
Surface Owner Private	Mineral Owner State
API No. 30-015-29447	

LOCATION OF RELEASE

Unit Letter M	Section 23	Township 18S	Range 26E	Feet from the 330	North/South Line South	Feet from the 330	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	-------------

Latitude 32.726745 Longitude -104.343405

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 15bbls	Volume Recovered 0bbls
Source of Release Transfer pump	Date and Hour of Occurrence August 19, 2013 time unknown	Date and Hour of Discovery August 19, 2013 at 9:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher of NMOCD	
By Whom? Chris Jones	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

RECEIVED
SEP 05 2013
NMOCD ARTESIA

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The Y-Strainer on a transfer pump clogged causing the water tank to overflow, releasing approximately 15bbls of water. Talon/LPE was contracted to perform an initial site assessment and soil sampling. Upon receipt of analytical results from the soil sampling activities, a work plan will be drafted and remedial activities will begin upon its approval.

Describe Area Affected and Cleanup Action Taken.*

The surface area of the release measures approximately 8X96 feet. Approximately 3 of the 15bbls are in the pasture.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>[Signature]</i>	OIL CONSERVATION DIVISION	
Printed Name: Chris Jones	Approved by Environmental Specialist: <i>[Signature]</i>	By: <i>[Signature]</i>
Title: HES Specialist	Approval Date: SEP 12 2013	Expiration Date:
E-mail Address: Christopher.Jones@oxy.com	Conditions of Approval: Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION	Attached <input type="checkbox"/>
Date: <i>9-5-13</i> Phone: 575-628-4121	PROPOSAL NO LATER THAN:	

* Attach. Additional Sheets If Necessary

October 2, 2013

2RP-1904