


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003  
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

**Release Notification and Corrective Action**

*njm* 1326251610/COG Production OPERATOR  Initial Report  Final Report

Name of Company	COG OPERATING LLC 217955	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Sidewinder #001H	Facility Type	Tank Battery

Surface Owner Private Mineral Owner Lease No. (API#) 30-015-38500

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	32	26S	29E					Eddy

Latitude 32.00143 Longitude 104.1374

**NATURE OF RELEASE**

Type of Release	Produced water	Volume of Release	20bbls	Volume Recovered	15bbls
Source of Release	4" metal load line	Date and Hour of Occurrence	09-03-2013	Date and Hour of Discovery	09-03-2013 3:00pm
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
A 1/4 inch hole developed in a 4" metal line. Replaced the 4" metal line with a plastic coated metal line.					
Describe Area Affected and Cleanup Action Taken.*					
Initially 20bbls of produced water were released due to a 1/4 inch hole developed by corrosion. We were able to recover 15bbls of produced water with a vacuum truck. The entire release was contained inside the lined facility. All free fluid has been recovered. Contaminated gravel has been removed and we have replaced with fresh gravel as necessary. This location has been returned to its prior condition.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					

Signature: <i>Robert Grubbs Jr.</i>		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Robert Grubbs Jr.		Approved by District Supervisor: Signed By <i>Mike Demore</i>	
Title: Senior Environmental Coordinator		Approval Date: SEP 19 2013	Expiration Date:
E-mail Address: rgrubbs@concho.com		Conditions of Approval:	
Date: 09-10-2013 Phone: 432-661-6601		Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

2RP-1913

## Bratcher, Mike, EMNRD

---

**From:** Robert Grubbs <RGrubbs@concho.com>  
**Sent:** Tuesday, September 10, 2013 3:07 PM  
**To:** Bratcher, Mike, EMNRD  
**Cc:** Robert McNeill  
**Subject:** C-141's Initial - Final Reports - Sidewinder #001H, F.U.N. State Com #001H, Down South State Com #001H and the Patton 5 Fee #002H  
**Attachments:** Sidewinder #001H ( Tank Battery ) -- Date of Release --09-03-2013.pdf; F.U.N. State Com #001H ( Tank Battery ) -- Date of Release -- 09-05-2013.pdf; Down South State Com #001H ( Tank Battery ) -- Date of Release -- 09-10-2013.pdf; Patton 5 Fee #002H ( Tank Battery ) -- Date of Release -- 09-10-2013.pdf



Mr. Bratcher,

Please see attached the C-141 Initial Reports for the following releases that occurred at our Sidewinder #001H, F.U.N. State Com #001H, Down South State Com #001H and the Patton 5 Fee #002H in Eddy County New Mexico. These are lined facilities.

Thank you,

*Robert Grubbs Jr.*  
*Sr. Environmental Coordinator*  
432.683.7443 (main)  
432.818.2369 (direct)  
432.661.6601 (cell)  
[rgrubbs@concho.com](mailto:rgrubbs@concho.com)  
Mailing Address:  
One Concho Center  
600 W. Illinois Avenue  
Midland, Texas 79701



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.