

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

*NJM/W 132673 1985*

*258462*

OPERATOR

Initial Report  Final Report

Name of Company	NADEL AND GUSSMAN HEYCO, LLC <i>258462</i> Contact	Keith Cannon or Tammy R. Link
Address	PO Box 1936, Roswell 88202-1936	Telephone No. (575) 623-6601
Facility Name	Hondo 4 Federal #1	Facility Type
Surface Owner	<i>USA Federal</i>	Mineral Owner State of New Mexico
		Lease No. API 30-015-25146

**LOCATION OF RELEASE**


Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	4	18S	31E	1980'	N	1,980'	W	Eddy

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release - 297 bbls of oil	Volume of Release 297	Volume Recovered 144 bbls of oil
Source of Release oil	Date/Hour of Release 9/18/13 2:35p	Date/Hour Discovered 9/19/13 11:15 a
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Reported to Terrie Draxton with BLM and Mike Bratcher with OCD.	
By Whom? Keith Cannon	Date and Hour 2:45 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

Bullplug was out of circulating line.

Describe Area Affected and Cleanup Action Taken.\*

Called vaccum truck to suck up free standing oil, most on location inside of dike, SW corner about 50 ft circle. Will dig up and be hauling it off. Will update with progress as cleanup continues.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tammy R. Link</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Tammy Link	Approved by District Supervisor: Signed By <i>Mike Bratcher</i>	
Title: Production Tech	Approval Date: <b>SEP 24 2013</b>	Expiration Date:
E-mail Address: tlink@heycoenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 9/20/13 Phone: (575)623-6601	Remediation per OCD Rule & Guidelines, & like approval by BLM. <b>SUBMIT REMEDIATION PROPOSAL NO LATER THAN:</b>	

\* Attach Additional Sheets If Necessary

*October 24, 2013*

*2RP-1928*