

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

**HOBBS OCD**  
**OCT 04 2013**  
**RECEIVED**

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**  Initial Report  Final Report

Name of Company Devon Energy	Contact Kenny Kidd
Address P.O. Box 250, Artesia, NM 88211	Telephone No. 575-748-3371
Facility Name Mad Dog 15 Federal Com #1	Facility Type Oil Well

Surface Owner	Mineral Owner	API No. 30-025-36778
---------------	---------------	----------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	15	23S	34E	660	SOUTH	660	EAST	LEA

Latitude 32.7271300239255 Longitude -103.909386055786

**NATURE OF RELEASE**

Type of Release Spill <b>PRODUCED WATER SKRL 10/4/13</b>	Volume of Release 20 bbls	Volume Recovered 0
Source of Release Water transfer line leak	Date and Hour of Occurrence <b>09/27/2013, 12:00pm</b>	Date and Hour of Discovery <b>09/27/2013, 12:00pm</b>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Trish Badbear BLM/ Jeff Leking OCD	<b>SKRL 10/4/13</b>
By Whom? Lynn Smith, Assistant Foreman	Date and Hour 9/27/2013, BLM 2:31pm, OCD 2:40pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

DTW = 285' SKRL 10/04/13

Describe Cause of Problem and Remedial Action Taken.\*

At the Mad Dog 15 -1, Lease Operator found a 20 barrel water leak on water transfer line .

Describe Area Affected and Cleanup Action Taken.\*

Lease operator went to the Mad Dod 15 fed com # 1 and found the water transfure line had a hole and put 20 BBLs of produced water across an area of 3' X 150'. All water soaked in the ground. None was recovered. The water line was cut and re-welded and put back into production.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Graciela C. Bustamante</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Graciela C. Bustamante	<i>Jeffrey Leking</i> Approved by Environmental Specialist Environmental Specialist	
Title: Field Admin. Tech	Approval Date: <b>10/04/13</b>	Expiration Date: <b>12/04/13</b>
E-mail Address: Gracie.Bustamante@dvn.com	Conditions of Approval: <b>DELINQUATE &amp; REMEDIATE PER OCD GUIDELINES</b>	Attached <input type="checkbox"/>
Date: 10/02/2013 Phone: 575-746-5561	<b>IRP-10-13-2969</b>	

\* Attach Additional Sheets If Necessary

SUBMIT FINAL C-141 BY  
12/04/13

OCT 07 2013

4