



District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Artesia, NM 88210
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

WJMW 1327548720

OPERATOR Initial Report Final Report

Name of Company	SM ENERGY COMPANY 154903	Contact	VICKIE MARTINEZ
Address	3300 N "A" STREET, BLDG 7-200 MIDLAND, TX 79705	Telephone No.	(432)688-1709
Facility Name	ESDU 34	Facility Type	WELL

Surface Owner	BUREAU OF LAND MANAGEMENT	Mineral Owner	BUREAU OF LAND MANAGEMENT	NPI No.	30-015-41615
---------------	---------------------------	---------------	---------------------------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	24	18S	31E	1500	NORTH	2020	EAST	EDDY

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	SPILL	Volume of Release	11.93 BBLS	Volume Recovered	0 BBLS
Source of Release	INJECTION LINE	Date and Hour of Occurrence	9/18/13 5:00 PM	Date of Report 9/18/13 5:00 PM	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	BLM-JAMES AMOS AND NMOCD-MIKE BRATCHER		
By Whom?	NATHAN LUOMA	Date and Hour	9/18/13 5:00 PM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*
N/A *(Per conversation with Vickie Martinez on 10/2/13 the release of 11.93 bbls was salt water)*

Describe Cause of Problem and Remedial Action Taken.*
WHILE BUILDING LOCATION, DOZER TRACKS SUNK INTO SOFT GROUND AND CUT AN INJ LINE BURIED 8 INCHES BELOW THE GROUND CAUSING SPILL.

Describe Area Affected and Cleanup Action Taken.*
AREA AFFECTED WAS 110' X 213'. REMOVED CONTAMINATED SOIL AND BRUSH AND HAULED TO A PERMITTED FACILITY. TETRA TECH TOOK INITIAL SOILS SAMPLES AND SENT TO LAB AND WE ARE WAITING ON RESULTS.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Vickie Martinez</i>	OIL CONSERVATION DIVISION	
Printed Name: VICKIE MARTINEZ	Approved by Environmental Specialist: Signed By <i>Mike Bratcher</i>	
Title: ENGINEER TECH II	Approval Date: OCT 02 2013	Expiration Date:
E-mail Address: VMARTINEZ@SM-ENERGY.COM	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 09/26/2013 Phone: (432)688-1709	Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	

* Attach Additional Sheets If Necessary

November 2, 2013 *2RP-1961*