

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

*nJMW1328150819* OPERATOR  Initial Report  Final Report

Name of Company <i>Americo Energy Resources, LLC 228051</i>	Contact Ehsan Bayat
Address <i>7575 San Felipe St ste 200 Houston TX 70063</i>	Telephone No. 713-984-9700
Facility Name <i>East Shugart Unit #56</i>	Facility Type SWD Pump in Battery
Surface Owner <i>FED</i>	Mineral Owner
API No. <i>30-015-27949</i>	

**LOCATION OF RELEASE**


Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	35	18S	31E					Eddy

Latitude *32.705124* Longitude *103.837797*

**NATURE OF RELEASE**

Type of Release <i>FSW Produced Water</i>	Volume of Release 20 bbls	Volume Recovered 15
Source of Release Main SWD line leak	Date and Hour of Occurrence 10/2/2013 11pm	Date and Hour of Discovery 11pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		

Describe Cause of Problem and Remedial Action Taken.\*  
There was a pin hole leak in the main SWD line inside the facility. 20 bbls of water released, 15 recovered. Vac truck came to location, cleaned and remediated



Describe Area Affected and Cleanup Action Taken.\*  
Vac truck came to location, cleaned and remediated *Soil Sample Analysis Required*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>[Signature]</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Ehsan Bayat	Approved by Environmental Specialist: signed By <i>[Signature]</i>	
Title: Project Evaluator/regulatory Analyst	Approval Date: <b>OCT 08 2013</b>	Expiration Date:
E-mail Address: ehsan.bayat@americoenergy.com	Conditions of Approval: Remediation per OCD Rule & Guidelines, & like approval by BLM. <b>SUBMIT REMEDIATION</b>	
Date 10/3/2013 Phone: 713-984-9700	Attached <input type="checkbox"/>	

**PROPOSAL NO LATER THAN:**  
*November 8, 2013* *2RP-1979*

\* Attach Additional Sheets If Necessary