


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised August 8, 2011

Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

*7JMW/22575191* OPERATOR  Initial Report  Final Report

Name of Company <i>Linn Operating</i> <i>269324</i>	Contact <i>Joe Hernandez</i>
Address <i>2130 W. Bender Blvd, Hobbs, NM 88240</i>	Telephone No. <i>575-738-1739</i>
Facility Name <i>J.L. Keel B #91</i>	Facility-Type <i>Oil</i>
Surface Owner <i>Federal</i>	Mineral Owner <i>Federal</i> API No. <i>30-015-28442</i>

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	8	17S	31E	2664	FSL	2562	FEL	Eddy

Latitude 32.84917° N Longitude 103.89088° W

**NATURE OF RELEASE**

Type of Release <i>Produced Water/Oil</i>	Volume of Release <i>10/5</i>	Volume Recovered <i>0/0</i>
Source of Release <i>Poly Pipeline</i>	Date and Hour of Occurrence <i>8/24/2012 11 am</i>	Date and Hour of Discovery <i>8/24/2012 11:30 am</i>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <i>M. Bratcher - NMOCD Terry Gregston - BLM</i>	
By Whom? <i>Gary Wink</i>	Date and Hour <i>8/29/2012 8am</i>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
While attempting to flush flow, line pressured up to 250 lbs. and the transition at well head ruptured. The pressurized fluid in the line sprayed out and onto the pad. A vacuum truck arrived and picked up less than 1 bbl of oil.

Describe Area Affected and Cleanup Action Taken.\*  
The spill affected approximately 1600 square feet of the well pad and 1800 square feet of pasture area to the southwest. The spill was delineated by Diversified Field Services, Inc. Impacted soils were removed to a NMOCD approved disposal facility. Confirmation samples were submitted to a commercial lab for analyses. Backfill of the excavation was approved by the NMOCD and BLM. The excavation was backfilled and the site was contoured to the surrounding landscape. The area was seeded with Lesser Prairie Chicken seed mix.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>[Signature]</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <i>Brian Wall</i>	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: <i>Construction Foreman</i>	Approval Date: <i>NOV 05 2013</i>	Expiration Date: <i>N/A</i>
E-mail Address: <i>bwall@linenergy.com</i>	Conditions of Approval: <i>N/A</i>	Attached <input type="checkbox"/>
Date: _____ Phone: <i>(432)363-9372</i>	<i>[Signature]</i>	

*2RP-1294*

\* Attach Additional Sheets If Necessary