


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

NJMW1331729774 OPERATOR Initial Report Final Report

Name of Company	COG OPERATING LLC <i>229137</i>	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Oxy Spumoni State #001	Facility Type	Tank Battery
Surface Owner	State	Mineral Owner	Lease No. (API#) 30-015-33089

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	16	17S	31E					Eddy

Latitude 32.82977 Longitude 103.86926

NATURE OF RELEASE

Type of Release	Oil and produced water	Volume of Release	1bbl of oil 510bbls of produced water	Volume Recovered	1bbl of oil 459bbls of produced water
Source of Release	Oil tank	Date and Hour of Occurrence	10-27-2013	Date and Hour of Discovery	10-27-2013 12:30pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher - NMOCD		
By Whom?	Michelle Mullins	Date and Hour	10-28-2013 07:42am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Water leg plugged upon the gun barrel, causing all the water from the gun barrel to go to the 210bbl oil tank. No alarm on oil tank. Clean out the plugged pipe and monitor.

Describe Area Affected and Cleanup Action Taken.*
Initially 1bbl of oil and 510bbls of produced water were released due to the water leg on the gun barrel was plugged. We were able to recover 1bbls of oil and 459bbls produced water with vacuum trucks. The majority of the spill was contained in the lined facility. A 50X75 area adjacent to the location. All free fluid has been recovered. BBC will sample the spill site area to delineate any possible contamination from the release and we will present a work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<i>Robert Grubbs Jr.</i>	OIL CONSERVATION DIVISION	
Printed Name:	Robert Grubbs Jr.	Approved by District Supervisor:	Signed By <i>Mike Bratcher</i>
Title:	Senior Environmental Coordinator	Approval Date:	NOV 12 2013
E-mail Address:	rgrubbs@concho.com	Expiration Date:	
Date:	11-7-2013	Phone:	432-661-6601

* Attach Additional Sheets If Necessary

Conditions of Approval:
Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:
December 12, 2013

Attached

2RP-2056

Bratcher, Mike, EMNRD

From: Robert Grubbs <RGrubbs@concho.com>
Sent: Thursday, November 07, 2013 1:06 PM
To: Bratcher, Mike, EMNRD
Cc: Robert McNeill; Cliff P. Brunson (cbrunson@bbcinternational.com); Ken Swinney <kswinney@bbcinternational.com> (kswinney@bbcinternational.com); Kathy Purvis (kathy@bbcinternational.com); jgilkey@bbcinternational.com
Subject: C-141 Initial Report - Oxy Spumoni State #001 (TB)
Attachments: Oxy Spumoni State #001 (TB) -- Date of Release -- 10-27-2013.pdf



Ladies and Gentlemen,

Please see attached the C-141 Initial release that occurred at our Oxy Spumoni State #001 (TB) on 10-27-2013 in Eddy County New Mexico. We plan to assess the spill area timely.

Thank you,

*Robert Grubbs Jr.
Sr. Environmental Coordinator*

432.683.7443 (main)

432.818.2369 (direct)

432.661.6601 (cell)

rgrubbs@concho.com

Mailing Address:

One Concho Center

600 W. Illinois Avenue

Midland, Texas 79701



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

Bratcher, Mike, EMNRD

From: Michelle Mullins <MMullins@concho.com>
Sent: Monday, October 28, 2013 6:42 AM
To: Amos, James (jamos@blm.gov); Bratcher, Mike, EMNRD
Cc: Robert Grubbs
Subject: Oxy Spumoni State #1 SWD

Mr. Amos, Mr. Bratcher:

At approximately 12:30 p.m. on 10/27/2013, a produced fluid release was discovered at the above-referenced facility. The fluid was mostly contained inside the battery which is lined with 40 mil plastic. An estimated 500 barrels of produced fluid was released. The cause of the release is currently under investigation. We will follow up within 15 days with a C-141 Report. GPS coordinates, legal description and driving directions are below.

N32.82978 W103.86926

Oxy Spumoni State #1 SWD
Unit P, Sec. 16 T17S R31E
Eddy County, NM
990' FSL & 990' FEL
API 30-015-33089

From Highway 82, travel east past Loco Hills. Turn north on CR 223 (Sweet Gum Road) and travel 1.2 miles. Turn east and travel .3 miles into location.

*Michelle Mullins:
Environmental Coordinator
COG Operating, LLC
(432) 934-1052;
mmullins@concho.com*

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.