


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

njmw1331739314

Name of Company		COG OPERATING LLC <i>217955</i>	Contact	Robert McNeill
Address		600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name		Copperhead 31 Federal Com #001H	Facility Type	Tank Battery
Surface Owner	Federal	Mineral Owner	Lease No. (API#) 30-015-38532	

OPERATOR Initial Report Final Report

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	31	26S	29E					Eddy

Latitude 32.00143 Longitude 104.01685

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	125bbbls	Volume Recovered	110bbbls
Source of Release	Oil tank	Date and Hour of Occurrence	10-29-2013	Date and Hour of Discovery	10-29-2013 2:30pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher - NMOCD		
By Whom?	Robert Grubbs Jr.	Date and Hour	10-30-2013 3:39pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
Oil tank ran over due to incorrect valve position. Check valve positioning.					
Describe Area Affected and Cleanup Action Taken.*					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					

Signature: <i>Robert Grubbs Jr.</i>		OIL CONSERVATION DIVISION	
Printed Name: Robert Grubbs Jr.		Approved by District Supervisor:	Signed By <i>Mike Bratcher</i>
Title: Senior Environmental Coordinator	Approval Date: NOV 13 2013	Expiration Date:	
E-mail Address: rgrubbs@concho.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 11-7-2013	Phone: 432-661-6601		


* Attach Additional Sheets If Necessary

Like approval by
BLM

2RP-2057

Bratcher, Mike, EMNRD

From: Robert Grubbs <RGrubbs@concho.com>
Sent: Thursday, November 07, 2013 4:05 PM
To: Amos, James <jamos@blm.gov> (jamos@blm.gov); Mike Burton (mburton@blm.gov) (mburton@blm.gov); Bratcher, Mike, EMNRD
Cc: Robert McNeill
Subject: C-141 Initial - Final Report - Copperhead 31 Federal Com#001H
Attachments: Copperhead 31 Federal Com #001H (TB) Initial - Final.pdf



Gentlemen,

Please see attached the C-141 Initial/Final Report for a release that occurred at our Copperhead 31 Federal Com#001H (TB) 10-29-2013 in Eddy County New Mexico. This is a lined facility.

Thank you,

*Robert Grubbs Jr.
Sr. Environmental Coordinator*

432.683.7443 (main)

432.818.2369 (direct)

432.661.6601 (cell)

rgrubbs@concho.com

Mailing Address:

One Concho Center

600 W. Illinois Avenue


Midland, Texas 79701



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

Bratcher, Mike, EMNRD

From: Robert Grubbs <RGrubbs@concho.com>
Sent: Wednesday, October 30, 2013 2:39 PM
To: Bratcher, Mike, EMNRD
Cc: Robert McNeill; Michelle Mullins
Subject: Copperhead "31" Federal Com #1H



Mr. Bratcher:

At approximately 2:30 p.m. on 10/29/2013, a produced fluid release was discovered at the above-referenced facility. An estimated 125 barrels of produced fluid was released. The cause of the release is currently under investigation. We will follow up within 15 days with a C-141 Report. GPS coordinates, legal description and driving directions are listed below.

32.09273 104.11140

***Copperhead "31" Federal Com #1H
Unit H Sec 31 T26S R29E
480' FSL & 480' FEL
Eddy County, NM
API 30-015-38532***

Thank you,

***Robert Grubbs Jr.
Sr. Environmental Coordinator
432.683.7443 (main)
432.818.2369 (direct)
432.661.6601 (cell)
rgrubbs@concho.com
Mailing Address:
One Concho Center
600 W. Illinois Avenue
Midland, Texas 79701***

