


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003  
Submit 2 Copies to appropriate  
Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

*njmw* 1331740377

**OPERATOR**

Initial Report  Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	G J West COOP Unit #191	Facility Type	Tank Battery

Surface Owner	State	Mineral Owner		Lease No. (API#)	30-015-36226
---------------	-------	---------------	--	------------------	--------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	22	17S	29E					Eddy

Latitude 32.82465 Longitude 104.06546

**NATURE OF RELEASE**

Type of Release	Oil and produced water	Volume of Release	5bbls of oil 30bbls of produced water	Volume Recovered	4bbls of oil 29bbls of produced water
Source of Release	Water tank	Date and Hour of Occurrence	11-01-2013	Date and Hour of Discovery	11-01-2013 07:30am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD			
By Whom?	Michelle Mullins	Date and Hour	11-01-2013 4:04pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

The water pump failed, causing the water tank to over flow.

Describe Area Affected and Cleanup Action Taken.\*

Initially 105bbls of oil and 30bbls of produced water were released and we were able to recover 4bbls of oil and 29bbls of produced water with a vacuum truck. The release was completely contained inside the lined facility. All free fluid has been recovered and contaminated gravel has been removed. Fresh gravel has been added to the facility as needed. This facility has been returned to its prior condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<i>Robert Grubbs Jr.</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name:	Robert Grubbs Jr.	Approved by District Supervisor:	Signed By <i>Mike Bratcher</i>
Title:	Senior Environmental Coordinator	Approval Date:	NOV 13 2013
E-mail Address:	rgrubbs@concho.com	Expiration Date:	
Date:	11-8-2013	Conditions of Approval:	Attached <input type="checkbox"/>
Phone:	432-661-6601		

\* Attach Additional Sheets If Necessary

2RP-2058

**Bratcher, Mike, EMNRD**

---

**From:** Robert Grubbs <RGrubbs@concho.com>  
**Sent:** Friday, November 08, 2013 9:26 AM  
**To:** Bratcher, Mike, EMNRD  
**Cc:** Robert McNeill  
**Subject:** C-141 Initial - Final Report - G J West Coop Unit #191  
**Attachments:** G J West COOP Unit #191 (TB) -- Date of Release -- 11-01-2013.pdf



*Mr. Bratcher,*

*Please see attached the C-141 Initial/Final Report for a release that occurred at our G J West Coop Unit #191 (TB) on 11-1-2013 in Eddy County New Mexico. This is a lined facility.*

*Thank you,*

*Robert Grubbs Jr.  
Sr. Environmental Coordinator  
432.683.7443 (main)  
432.818.2369 (direct)  
432.661.6601 (cell)  
[rgrubbs@concho.com](mailto:rgrubbs@concho.com)  
Mailing Address:  
One Concho Center  
600 W. Illinois Avenue  
Midland, Texas 79701*



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

## Bratcher, Mike, EMNRD

---

**From:** Michelle Mullins <MMullins@concho.com>  
**Sent:** Friday, November 01, 2013 3:04 PM  
**To:** Bratcher, Mike, EMNRD  
**Cc:** Robert Grubbs  
**Subject:** GJ West Coop Unit #191

Mr. Bratcher:

At approximately 7:30 a.m. on 11/01/2013, a produced fluid release was discovered at the above-referenced facility. An estimated 35 barrels of produced fluid was released. The cause of the release is currently under investigation. We will follow up within 15 days with a C-141 Report. GPS coordinates, legal description and driving directions are listed below.

32.82465 104.06529

GJ West Coop Unit #191  
Unit C Sec 22 T17S R29E  
990' FNL & 1770' FWL  
Eddy County, NM  
API 30-015-36226

On Highway 82, travel east from Artesia. Turn north onto Barnaval Draw Road. Facility is the first one on the right.

Michelle Mullins  
Environmental Coordinator  
COG Operating, LLC  
(432) 934-1052  
[mmullins@concho.com](mailto:mmullins@concho.com)

*CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.*

**CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.**

**Warren, JeanMarie, EMNRD**

---

**From:** Robert Grubbs <RGrubbs@concho.com>  
**Sent:** Thursday, November 14, 2013 1:08 PM  
**To:** Warren, JeanMarie, EMNRD  
**Subject:** RE: This is jean with OCD

*Ms. Warren,*

*Per our discussion on the phone yesterday, the spill on the G J West Coop Unit #191 (TB). The amount release was 5bbls of oil, not 105. Sorry for the mix up, If you any other question please feel free to contact me.*

*Thank you,*

**Robert Grubbs Jr.**  
**Sr. Environmental Coordinator**  
432.683.7443 (main)  
432.818.2369 (direct)  
432.661.6601 (cell)  
[rgrubbs@concho.com](mailto:rgrubbs@concho.com)  
**Mailing Address:**  
**One Concho Center**  
**600 W. Illinois Avenue**  
**Midland, Texas 79701**



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.