


District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised August 8, 2011

Operator must submit copies to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nJMW1321135743

OPERATOR

Initial Report Final Report

Name of Company	Chevron USA Inc. <i>4323</i>	Contact	David A. Pagano
Address	15 Smith Rd., Midland, TX, 79705	Telephone No.	wk: 575-396-4414X275 cell: 505-787-9816
Facility Name	TexMack BTY	Facility Type	Oil Production Batteries
Surface Owner	Federal	Mineral Owner	Federal
		API No. 30-015-29720) Closest Well Texmack 11-1)	

Latitude: 32.853570 / Longitude: -103.843080

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	11	17S	31E	990	North	1650	West	Eddy

NATURE OF RELEASE

Type of Release	Flare	Volume of Release	1095	Volume Recovered	0 MSCF
Source of Release	Flare	Date and Hour of Occurrence	07/28/13 06:00PM	Date and Hour of Discovery	07/28/13 06:00PM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Bratcher, Mike, EMNRD		
By Whom?	Date and Hour 07/29/13 4:30 PM				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.* N/A					
Describe Cause of Problem and Remedial Action Taken.* Frontier shut in sales line to complete maintenance/expansion at Maljamar Gas Plant. Chevron stayed in close contact with frontier in order to stop flaring as soon as they were able to accept our gas in the sales line.					
Describe Area Affected and Cleanup Action Taken.* NA					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature: <i>David Pagano</i>		OIL CONSERVATION DIVISION			
Printed Name: David A. Pagano		Approved by Environmental Specialist: Signed By <i>Mike Bratcher</i>			
Title: Health & Environmental Specialist		Approval Date: SEP 04 2013		Expiration Date:	
E-mail Address: dpgn@chevron.com		Conditions of Approval:			Attached <input type="checkbox"/>
Date: 08/13/13 Phone: 505-787-9816					

* Attach Additional Sheets If Necessary

2RP-1775

Closed JM
SEP 04 2013

Bratcher, Mike, EMNRD

From: Pagano, David (David.Pagano) <David.Pagano@chevron.com>
Sent: Tuesday, August 13, 2013 6:29 AM
To: Pagano, David (David.Pagano); Bratcher, Mike, EMNRD
Cc: Moschetti, Nick (NMOS); DeLeon, Josepha; Nevarez, Joseph D
Subject: RE: Initial C-141 & C-129 reports for the flaring at our Skelly 907, Skelly 940 & TexMack Batteries due to Frontier shutting in our sales line
Attachments: 20130728 C-141_SKU 940 Bty Flare FS.pdf; 20130728 C-141 Skelly 907 Bty Flare FS.pdf; 20130728 C-141 TexMack Bty Flare FS.pdf

Mike,

Here are the final reports for the flaring at our Skelly 907, Skelly 940 & TexMack Batteries due to Frontier shutting in our sales line.

Regards,

David A. Pagano

MCA Health & Environmental Specialist (Central Permian – Vacuum/Buckeye, Dollarhide & Sundown)

56 Texas Camp Rd., Lovington, NM 88260

☎ Phone: 575-396-4414 x275

☎ Cell: 505-787-9816

☎ Fax: 575-396-6913

dpgn@chevron.com

"CONFIDENTIALITY NOTICE: This message is confidential and may be privileged. If you believe that this email has been sent to you in error, please reply to the sender that you received the message; then please delete this email."

From: Pagano, David (David.Pagano)
Sent: Monday, July 29, 2013 5:09 PM
To: Pagano, David (David.Pagano); Bratcher, Mike, EMNRD
Cc: Moschetti, Nick (NMOS); DeLeon, Josepha; Nevarez, Joseph D
Subject: Initial C-141 & C-129 reports for the flaring at our Skelly 907, Skelly 940 & TexMack Batteries due to Frontier shutting in our sales line

Mike,

Here are the Initial C-141 & C-129 reports for the flaring at our Skelly 907, Skelly 940 & TexMack Batteries due to Frontier shutting in our sales line. Flaring started at 6:00PM on 7/28/13. They expect to be down from 7-10 days. Once the sales line is back up and we are no longer flaring I will send the final reports. You will find the wells associated with each battery at the bottom of the email. Please let me know if you have any questions or need additional information.

Regards,

David A. Pagano

MCA Health & Environmental Specialist (Central Permian – Vacuum/Buckeye, Dollarhide & Sundown)

56 Texas Camp Rd., Lovington, NM 88260

☎ Phone: 575-396-4414 x275

☎ Cell: 505-787-9816

☎ Fax: 575-396-6913

dpgn@chevron.com

"CONFIDENTIALITY NOTICE: This message is confidential and may be privileged. If you believe that this email has been sent to you in error, please reply to the sender that you received the message; then please delete this email."

Well	Battery
SU 689	SKELLY UNIT
SU 699	SKELLY UNIT
SU 700	SKELLY UNIT
SU 703	SKELLY UNIT
SU 707	SKELLY UNIT
SU 711	SKELLY UNIT
SU 713	SKELLY UNIT
SU 714	SKELLY UNIT
SU 718	SKELLY UNIT
SU 719	SKELLY UNIT
SU 722	SKELLY UNIT
SU 724	SKELLY UNIT
SU 725	SKELLY UNIT
SU 828	SKELLY UNIT
SU 907	SKELLY UNIT
SU 908	SKELLY UNIT
SU 912	SKELLY UNIT
SU 914	SKELLY UNIT
SU 930	SKELLY UNIT
SU 931	SKELLY UNIT
SU 933	SKELLY UNIT
SU 936	SKELLY UNIT
SU 937	SKELLY UNIT