

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

njmw/333029835

OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company Devon Energy Prod. 6137		Contact Tracy Kidd	
Address PO Box 250 Artesia, NM 88211		Telephone No. 575.513.0628	
Facility Name Cotton Draw Unit 114		Facility Type Oil Well	

Surface Owner Federal	Mineral Owner	API No. 3001537410
------------------------------	---------------	---------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	34	24S	31E	330	North	1980	East	Eddy

Latitude: 32.180117040773 Longitude: 103.763554613439

NATURE OF RELEASE

Type of Release Spill Oil	Volume of Release 60bbls	Volume Recovered 50bbls
Source of Release mechanical failure blown gasket on a heater treater	Date and Hour of Occurrence 11/16/2013	Date and Hour of Discovery 11/16/2013, 9:49PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Tracy Kidd- Production Foreman	
By Whom? Chris McCullough	Date and Hour 11/16/2013	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken.*

Gasket rupture on fire tube in heater treater caused oil spray. RW Trucking recovered 50bbls of oil and soil samples will be taken. Gasket was replaced on heater treater.

RECEIVED

Describe Area Affected and Cleanup Action Taken.*

Oil spill remained on location. RW Trucking recovered 50bbls and soil sampling will be done.

NOV 20 2013
NMOCB

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Sandra Farley</i>	OIL CONSERVATION DIVISION	
Printed Name: Sandra Farley	Approved by Environmental Specialist	Signed By <i>Mike Beaman</i>
Title: Field Admin Support	Approval Date: NOV 26 2013	Expiration Date:
E-mail Address: Sandra.Farley@dvn.com	Conditions of Approval:	
Date: 11/19/2013 Phone: 575.746.5587	Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION PROPOSAL NO LATER THAN: December 26, 2013	
		Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

2RP-2076