

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brzoz Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
DEC 11 2013
Form C-141 Revised October 10, 2003
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form
NMOCD AR

Release Notification and Corrective Action

njm *1334728810* **OPERATOR** Initial Report Final Report

Name of Company	COG OPERATING LLC <i>229/137</i>	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Central Battery	Facility Type	Tank Battery
Surface Owner	Federal	Mineral Owner	Lease No. (API#) 30-015-27764

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	24	17S	29E					Eddy
				Latitude 32.819		Longitude 104.025		

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	12bbls	Volume Recovered	10bbls
Source of Release	Steal breaded hose	Date and Hour of Occurrence	11-30-2013	Date and Hour of Discovery	11-30-2013 07:00am
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
Steal breaded hose failed on discharged pressure on murphy. Replace hose.					
Describe Area Affected and Cleanup Action Taken.*					
Initially 12bbls of produced water were released due to a failed breaded hose on murphy. We were able to recover 10bbls of produced water with a vacuum truck. All free fluid has been recovered. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a work plan to the BLM/NMOCD for approval prior to any significant remediation work					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature: <i>Robert Grubbs Jr.</i>		OIL CONSERVATION DIVISION			
Printed Name: Robert Grubbs Jr.		Approved by District Supervisor:		Signed By: <i>Mike Brandon</i>	
Title: Senior Environmental Coordinator		Approval Date: DEC 13 2013		Expiration Date:	
E-mail Address: rgrubbs@concho.com		Conditions of Approval:			Attached <input type="checkbox"/>
Date: 12-11-2013 Phone: 432-661-6601		Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:			


* Attach Additional Sheets If Necessary

PROPOSAL NO LATER THAN:
January 13, 2013

2RP-2112

Bratcher, Mike, EMNRD

From: Robert Grubbs <RGrubbs@concho.com>
Sent: Wednesday, December 11, 2013 6:51 PM
To: Mike Burton (mburton@blm.gov) (mburton@blm.gov); Amos, James <jamos@blm.gov> (jamos@blm.gov); Bratcher, Mike, EMNRD
Cc: Robert McNeill; Tavaréz, Ike; Kujawski, Marcus (Marcus.Kujawski@tetrattech.com)
Subject: C-141 Initial Report - Central Battery
Attachments: Central Battery (TB) -- Date of Release -- 11-30-2013.pdf



Gentlemen,

Please see attached the C-141 Initial Report for a release that occurred at our Central Battery (TB) on 11-30-2013 in Eddy County New Mexico. We plan to assess the spill area timely.

Thank you,

*Robert Grubbs Jr.
Sr. Environmental Coordinator
432.683.7443 (main)
432.818.2369 (direct)
432.661.6601 (cell)
rgrubbs@concho.com*

*Mailing Address:
One Concho Center
600 W. Illinois Avenue
Midland, Texas 79701*



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.