


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

AMW1334731295

OPERATOR

Initial Report Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Amber Cannon
Address 105 S. 4 TH Street	Facility Name Martha AIK Federal #1	Telephone No. 575-748-1471
Facility Name Martha AIK Federal #1	API Number 30-015-26549	Facility Type Battery/Tin Horn
Surface Owner Federal	Mineral Owner Federal	Lease No. NM-65417

LOCATION OF RELEASE

Unit Letter P	Section 11	Township 22S	Range 31E	Feet from the 330'	North/South Line South	Feet from the 430'	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.39966 Longitude 103.74086

NATURE OF RELEASE

Type of Release Produced Water; Crude Oil	Volume of Release ¹ 100 B/PW; 1 B/O	Volume Recovered 50 B/PW; 0 B/O
Source of Release Water transfer line	Date and Hour of Occurrence 12/3/2013; PM	Date and Hour of Discovery 12/3/2013, PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/NMOCD II	
By Whom? Robert Asher/Yates Petroleum Corporation	Date and Hour 12/4/2013; AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
A water transfer line east of the battery at the tin horn ruptured.

Describe Area Affected and Cleanup Action Taken.*
Release occurred at the tin horn and flowed south along the pipeline right-of-way. All wells were turned off, valves were closed, foreman was notified and crews were called to fix the water line. A crew was called to do initial clean-up of the area, and all excavated soils were disposed of at an approved NMOCD facility. Vertical and horizontal delineation samples will be taken and sent to a NMOCD approved facility. **Depth to Ground Water: >100' (approximately 150', Section 11, T22S-R31E, per Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Amber Cannon</i>	OIL CONSERVATION DIVISION	
Printed Name: Amber Cannon	Approved by District Supervisor	Signed By <i>Mike Bratcher</i>
Title: Environmental Regulatory Agent	Approval Date: DEC 13 2013	Expiration Date:
E-mail Address: acannon@yatespetroleum.com	Conditions of Approval: Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION	Attached <input type="checkbox"/>
Date: Thursday, December 12, 2013 Phone: 575-748-4111	PROPOSAL NO LATER THAN:	

* Attach Additional Sheets If Necessary

January 13, 2013 **2RP-2113**

Bratcher, Mike, EMNRD

From: Amber Cannon <ACannon@yatespetroleum.com>
Sent: Thursday, December 12, 2013 8:46 AM
To: Bratcher, Mike, EMNRD; Dade, Randy, EMNRD; jamos@blm.gov; dwhitloc@blm.gov
Cc: Bob Asher
Subject: RE: Release (Livingston Ridge SWD Waterline)
Attachments: MarthaAIKFederal1TH_C141_120313 Initial.pdf

Please find attached an initial C-141 for the release below.

Thanks,
Amber

From: Bob Asher
Sent: Friday, December 06, 2013 2:09 PM
To: (mike.bratcher@state.nm.us); (Randy.Dade@state.nm.us); jamos@blm.gov; dwhitloc@blm.gov
Cc: Amber Cannon; Katie Parker; Lupe Carrasco
Subject: RE: Release (Livingston Ridge SWD Waterline)

After meters within the system were checked this is an update for the estimated release amount from the Livingston Ridge SWD Waterline, reported on 12/4/2013.

Released: 1 B/O and 100 B/PW; Recovered: 0 B/O and 50 B/PW.

Thank you.

Robert Asher
Yates Petroleum Corporation
boba@yatespetroleum.com

From: Bob Asher
Sent: Wednesday, December 04, 2013 9:56 AM
To: (mike.bratcher@state.nm.us); (Randy.Dade@state.nm.us); jamos@blm.gov; dwhitloc@blm.gov
Cc: Amber Cannon; Katie Parker; Lupe Carrasco
Subject: Release (Livingston Ridge SWD Waterline)

Yates Petroleum Corporation is reporting a release at the following location (12/3/2013).

Livingston Ridge SWD Waterline (east of the Martha AIK Federal #1 Battery)
30-015-26549
Section 11, T22S-R31E
Eddy County, New Mexico

Released: 300 B/PW; Recovered: 50 B/PW

Release was from a surface flow line in a tinhorn east of the battery. Wells shut in. Vacuum truck(s) were called and crews called to repair line.

A Form C-141 Initial will be submitted with complete information.

Thank you.

Robert Asher

NM Environmental Regulatory Supervisor

Yates Petroleum Corporation

105 S. 4th Street

Artesia, NM 88210

575-748-4217 (Office)

575-365-4021 (Cell)

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.

Bratcher, Mike, EMNRD

From: Bob Asher <BobA@yatespetroleum.com>
Sent: Wednesday, December 04, 2013 9:56 AM
To: Bratcher, Mike, EMNRD; Dade, Randy, EMNRD; jamos@blm.gov; dwhitloc@blm.gov
Cc: Amber Cannon; Katie Parker; Lupe Carrasco
Subject: Release (Livingston Ridge SWD Waterline)

Yates Petroleum Corporation is reporting a release at the following location (12/3/2013).

Livingston Ridge SWD Waterline (east of the Martha AIK Federal #1 Battery)
30-015-26549
Section 11, T22S-R31E
Eddy County, New Mexico

Released: 300 B/PW; Recovered: 50 B/PW

Release was from a surface flow line in a tinhorn east of the battery. Wells shut in. Vacuum truck(s) were called and crews called to repair line.

A Form C-141 Initial will be submitted with complete information.

Thank you.

Robert Asher
NM Environmental Regulatory Supervisor
Yates Petroleum Corporation
105 S. 4th Street
Artesia, NM 88210
575-748-4217 (Office)
575-365-4021 (Cell)

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.

Bratcher, Mike, EMNRD

From: Bob Asher <BobA@yatespetroleum.com>
Sent: Friday, December 06, 2013 2:09 PM
To: Bratcher, Mike, EMNRD; Dade, Randy, EMNRD; jamos@blm.gov; dwhitloc@blm.gov
Cc: Amber Cannon; Katie Parker; Lupe Carrasco
Subject: RE: Release (Livingston Ridge SWD Waterline)

After meters within the system were checked this is an update for the estimated release amount from the Livingston Ridge SWD Waterline, reported on 12/4/2013.

Released: 1 B/O and 100 B/PW; Recovered: 0 B/O and 50 B/PW.

Thank you.

Robert Asher
Yates Petroleum Corporation
boba@yatespetroleum.com

From: Bob Asher
Sent: Wednesday, December 04, 2013 9:56 AM
To: (mike.bratcher@state.nm.us); (Randy.Dade@state.nm.us); jamos@blm.gov; dwhitloc@blm.gov
Cc: Amber Cannon; Katie Parker; Lupe Carrasco
Subject: Release (Livingston Ridge SWD Waterline)

Yates Petroleum Corporation is reporting a release at the following location (12/3/2013).

Livingston Ridge SWD Waterline (east of the Martha AIK Federal #1 Battery)
30-015-26549
Section 11, T22S-R31E
Eddy County, New Mexico

Released: 300 B/PW; Recovered: 50 B/PW

Release was from a surface flow line in a tinhorn east of the battery. Wells shut in. Vacuum truck(s) were called and crews called to repair line.

A Form C-141 Initial will be submitted with complete information.

Thank you.

Robert Asher
NM Environmental Regulatory Supervisor
Yates Petroleum Corporation
105 S. 4th Street
Artesia, NM 88210
575-748-4217 (Office)
575-365-4021 (Cell)

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.
