


District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised August 8, 2011
Appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

RTMW1335329102

OPERATOR

Initial Report Final Report

Name of Company	Lime Rock Resources II-A, L.P. 277558	Contact	Michael Barrett
Address	1111 Bagby Street Suite 4600, Houston, TX 77002	Telephone No.	575-623-8424
Facility Name	Federal T Transfer Station	Facility Type	Produced Water Transfer Station
Surface Owner	COG	Mineral Owner	Federal
		API No.	30-015-26404

LOCATION OF RELEASE *Federal T SWD #1*

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	12	18S	27E	660	North	990	East	Eddy County

Latitude 32.767150 Longitude 104.226800

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	2247 bbls	Volume Recovered	1987 bbls
Source of Release	Tank Battery	Date and Hour of Occurrence	Mid Morning on 10/31/13	Date and Hour of Discovery	10/31/13 @ 1:30 pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Jim Amos w/ BLM and Randy Dade w/ OCD		
By Whom?	Michael Barrett	Date and Hour	10/31/13 5:30 & 5:45pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	N/A		
If a Watercourse was Impacted, Describe Fully.* N/A					
Describe Cause of Problem and Remedial Action Taken.* Produced water tanks overflowed filling steel containment which then ran over on to location. Location has caliche berms, keeping release on site. Plan to pick up saturated soil and replace with clean caliche.					
Describe Area Affected and Cleanup Action Taken.* Hard packed caliche. Picked up all standing fluid.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					

OIL CONSERVATION DIVISION

Signature: <i>[Signature]</i>	Approved by Environmental Specialist: Signed By <i>[Signature]</i>	
Printed Name: Michael Barrett	Approval Date: DEC 19 2013	Expiration Date:
Title: Production Supervisor	Conditions of Approval: Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION	
E-mail Address: mbarrett@limerockresources.com	Attached <input type="checkbox"/>	
Date: 11/01/2013	Phone: 575-623-8424	

* Attach Additional Sheets If Necessary

PROPOSAL NO LATER THAN:
January 19, 2013

2RP-2117