


District I:
1625 N. French Dr., Hobbs, NM 88240
District II:
811 S. First St., Artesia, NM 88210
District III:
1000 Rio Brazos Road, Aztec, NM 87410
District IV:
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised August 8, 2011

Release Notification and Corrective Action

nJMW 1335336548

OPERATOR

Initial Report Final Report

Name of Company: Cimarex Energy Company <i>162683</i>	Contact: Johnny Titsworth
Address: 600 N. Marienfield, Suite 600, Midland, TX 79701	Telephone No. (432)250-2059
Facility Name: Texas 32 State TB	Facility Type: Tank Battery

Surface Owner: State	Mineral Owner:	AP No: 30-015-39110
----------------------	----------------	---------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	32	18	26	330	FNL	990	FWL	Eddy

Latitude: 32.71081 Longitude: 104.40968

NATURE OF RELEASE

Type of Release: Oil and Produced Water	Volume of Release: 45 / 45	Volume Recovered: 45 / 45
Source of Release: FWKO	Date & Hour of Occurrence: 12/17/13 0700	Date & Hour of Discovery: 12/17/13 0800
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? James Tinney	
By Whom? Nippy Howard	Date and Hour: 12/17/13 0800	
Was a Watercourse Reached? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Gasket on FWKO (free water knock-out) leaked. FWKO was isolated and used a vacuum truck to recover standing fluids.

Describe Area Affected and Cleanup Action Taken.*
Majority of spill was contained inside lined facility, with a 200'x200' overspray area on the pad, and a 100'x100' overspray area in the pasture. Pad area has been scraped and the impacted soil will be hauled to disposal, pasture area will be micro-blazed to neutralize hydrocarbons.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Johnny Titsworth	Approved by Environmental Specialist: Signed By <i>Mike Deacon</i>	
Title: Environmental Compliance Coordinator	Approval Date: DEC 19 2013	Expiration Date:
E-mail Address: jtitsworth@cimarex.com	Conditions of Approval: Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	Attached <input type="checkbox"/>

Date: 12/18/13 Phone: (432)-250-2059

* Attach Additional Sheets If Necessary

January 19, 2013
2RP-2124

Bratcher, Mike, EMNRD

From: Johnny Titsworth <jtitsworth@cimarex.com>
Sent: Wednesday, December 18, 2013 1:59 PM
To: Bratcher, Mike, EMNRD
Cc: Christine Alderman; James Tinney; Nicholas Koch
Subject: Texas 32 State TB
Attachments: Texas 32 TB.pdf

Follow Up Flag: Follow up
Flag Status: Completed

Mike,
I have attached the C-141 for the spill that occurred on the Texas 32 State TB. Almost all of the entire spill was contained inside the lined containment. There was some overspray on the pad and in the pasture. The pad has been scraped and the impacted soil will be hauled to disposal. We will apply micro-blaze on the pasture area. If you need anything else, feel free to contact us.

Johnny Titsworth
Environmental Compliance Coordinator
600 N. Marienfeld St., Suite 600
Midland, TX 79701
Mobile: 432-250-2059
Office: 432-620-1983

