

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

HOBBS OCD

JUL 18 2013

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

(162683)

OPERATOR

Initial Report Final Report

| | |
|---|-----------------------------|
| Name of Company: Cimarex Energy Company | Contact: Johnny Titsworth |
| Address: 600 N. Marienfield, Suite 600, Midland, TX 79701 | Telephone No. (432)250-2059 |
| Facility Name: Red Hills 28 SWD | Facility Type: Battery |
| Surface Owner: Federal | Mineral Owner: |
| API No. 30-025-35598 | |

LOCATION OF RELEASE

| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| M | 32 | 25 | 33 | 660 | RSL | 660 | FWL | Lea |

Latitude: 32.09631 Longitude: -103.58338

NATURE OF RELEASE

| | | |
|--|--|---|
| Type of Release: produced water | Volume of Release: 35 | Volume Recovered: 0 |
| Source of Release: | Date & Hour of Occurrence: 7/14/13 1700 | Date & Hour of Discovery: 7/15/13 1000 |
| Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? John Osborne | |
| By Whom? | Date and Hour: | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse: | |



If a Watercourse was Impacted, Describe Fully.*

DTW = 200' SWRL 7/18/13

Describe Cause of Problem and Remedial Action Taken.*
Injection line spurn a leak between injection pump and the well.

Describe Area Affected and Cleanup Action Taken.*
40' x 50' area on pad with no standing fluid, and approximately 10' x 15' area off location on Northeast side of pad. Location will be assessed and a work plan will be submitted for approval.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | |
|--|---|-----------------------------------|
| Signature:  | OIL CONSERVATION DIVISION | |
| Printed Name: Johnny Titsworth | Approved by Environmental Specialist  | |
| Title: Environmental Compliance Coordinator | Approval Date: 7/18/13 | Expiration Date: 9/18/13 |
| E-mail Address: jtitsworth@cimarex.com | Conditions of Approval: SUBMIT FINAL C-141 BY 9/18/13 | Attached <input type="checkbox"/> |
| Date: 7/18/13 | Phone: (432)-250-2059 | WRP-01-14-3005 |

* Attach Additional Sheets If Necessary

JAN 23 2014

