

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OCD
JAN 16 2014
RECEIVED

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company Devon Energy	Contact Tracy Kidd		
Address PO Box 250 Artesia, NM 88211	Telephone No. 575- 513.0628		
Facility Name: Trionyx 6 Fed 7 & 8	Facility Type Oil Well		
Surface Owner Federal	Mineral Owner	API No. 3002540047	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	6	25S	32E	200	South	685	East	Lea

Latitude: 32.1524569 _____ Longitude: -103.70759

NATURE OF RELEASE

Type of Release Spill Produced Water	Volume of Release 10bbls	Volume Recovered 2bbls
Source of Release mechanical failure: Load line valve left open	Date and Hour of Occurrence 01.13.2014; 2:45 PM	Date and Hour of Discovery 01.13.2014; 2:45 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Tracy Kidd- Production Foreman	
By Whom? Joe Wilks	Date and Hour 01.13.2014	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*

N/A

DTW = 350' JARL 1/16/14

Describe Cause of Problem and Remedial Action Taken.*

Water hauler driver failed to close load line valve after water pick up. Valve closed and 2 bbls of the 10bbls were recovered by vac truck.

Describe Area Affected and Cleanup Action Taken.*

Produced water spill remained on location affecting 75ft x 10Ft, equaling 10bbls. RW trucking recovered 2bbls with vac truck. Affected soil will be sampled, removed and replaced with fresh soil. Sampling will be completed by Talon LPE.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Sandra Farley</i>	OIL CONSERVATION DIVISION <i>Sandra Farley</i>	
Printed Name: Sandra Farley	Approved by Environmental Environmental Specialist	
Title: Field Admin Support	Approval Date: 1/16/14	Expiration Date: 3/17/14
E-mail Address: Sandy.Farley@dvn.com	Conditions of Approval: SUBMIT FINAL	Attached <input type="checkbox"/>
Date: 01.14.2014 Phone: 575.746.5587	C-141 BY 3/17/14	IRP-01-14-3008

* Attach Additional Sheets If Necessary

JAN 23 2014

RECEIVED

DATE

TIME

RW TRUCKING LLC

575-706-6506

1-19-14 NAME Tom DeCero TRUCK # 570

PHONE 714-214-6571

DATE 01/19/14 TIME 11:45

F GAUGE 1199

WATER GAUGE 1110

LINE

OFF

IN

150

END

END


END


END

RECEIVED

JAN 14 2006

RECEIVED







HOBBS OCD

JAN 14 2014

RECEIVED



HOVARS OGD
JAN 14 2013
RECEIVED



HOBBS OCD

JAN 14 2014

RECEIVED