

District I
1625 N. French Dr., Hobbs, NM 88249
 District II
1301 W. Grand Avenue, Artesia, NM 88210
 District III
1000 Rio Brazos Road, Aztec, NM 87410
 District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OCD

State of New Mexico
 Energy Minerals and Natural Resources
 Oil Conservation Division
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

Form C-141
 Revised October 10, 2003

Submit 2 Copies to appropriate
 District Office in accordance
 with Rule 116 on back
 side of form

RECEIVED

JAN 16 2014

Release Notification and Corrective Action

(B1559)

OPERATOR

Initial Report Final Report

Name of Company	PURVIS OPERATING CO.	Contact	Donnie E. Brown
Address	PO Box 51990, Midland, TX 79710	Telephone No.	432-682-7346
Facility Name	STATE 15 #001 JRL 1/16/14	Facility Type	Tank Battery (Heater Treater)

Surface Owner	State of New Mexico	Mineral Owner	State of New Mexico	Lease No.
---------------	---------------------	---------------	---------------------	-----------

LOCATION OF RELEASE API # 30.025.23528 JRL 01/16/14

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	15	10-S	34E 3E	1980	North	1980	West	Lea

JRL 1/16/14

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Oil and Water	Volume of Release	3-4 bbls	Volume Recovered	2 to 3 bbls.
Source of Release	Heater Treater	Date and Hour of Occurrence	1-11-14	Date and Hour of Discovery	1-11-2014, p.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	New Mexico OCD		
By Whom?	Justin Johnson	Date and Hour	p.m., 1-11-2014		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*
 DTW = 45' JRL 1/16/14

Describe Cause of Problem and Remedial Action Taken.*
 Hole in heater treater. Vacuum up spill.

Describe Area Affected and Cleanup Action Taken.*
 Area around heater treater and small area beyond tank battery pad. The clean-up action will be to pick up the oil stained caliche soil and replace with fresh caliche or soil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Donnie Brown by Betty Oxford</i>	OIL CONSERVATION DIVISION <i>Stephany Perkins</i> Environmental Specialist	
Printed Name: Donnie E. Brown	Approved by District Supervisor	
Title: Petroleum Engineer	Approval Date: 1/16/14	Expiration Date: 3/17/14
E-mail Address: eng@purvisop.com	Conditions of Approval: SUBMIT FINAL C-141 BY 3/17/14	Attached <input type="checkbox"/>
Date: Jan. 13, 2014 Phone: 432-682-7346		IRP-01-14-3009

* Attach Additional Sheets If Necessary

JAN 23 2014

R