

HOBBS OCD

HOBBS OCD

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011
Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.
RECEIVED

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	Oxy Permian	Contact	Tony Aguilar
Address	1017 W. Stanolind Road	Telephone No.	(575) 397-8251
Facility Name	North Hobbs Unit Satellite #27	Facility Type	Satellite

Surface Owner	State	Mineral Owner	API No. 30-025-07410
---------------	-------	---------------	----------------------

LOCATION OF RELEASE

NEAREST WELL NHU (GISA)
131

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	27	18S	38E					Lea County, NM

Latitude N 32.713656° Longitude W 103.143447°

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	80 bbls	Volume Recovered	5 bbls
Source of Release	Line on separator froze and caused tank overflow	Date and Hour of Occurrence	11/23/2013 @ 8:30 am	Date and Hour of Discovery	11/23/2013 @ 8:45 am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Geoffrey Leking, NMOCD		
By Whom?	Tony Aguilar	Date and Hour	01/24/2013 @ 9:10 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*
DTW = 57' SJRL 12/6/13

Describe Cause of Problem and Remedial Action Taken.*
The freezing of a gas line on a separator forced a tank overflow and caused 80 bbls of produced water to leak onto the ground. 5 bbls of fluids were recovered via vacuum truck and the line was repaired or replaced.

Describe Area Affected and Cleanup Action Taken.*
The area affected was approximately 305' x 20' and was contained on the location pad. Remediation will be completed in accordance with a plan approved by NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Aguilar</i>	OIL CONSERVATION DIVISION	
Printed Name: Tony Aguilar	Approved by Environmental Specialist: <i>Geoffrey Leking</i> Environmental Specialist	
Title: HES Specialist	Approval Date: 12/6/13	Expiration Date: 2/6/14
E-mail Address: Raymon_Aguilar@oxy.com	Conditions of Approval: SUBMIT FINAL C-141 BY 2/6/14	Attached <input type="checkbox"/>
Date: 12-4-13 Phone: (575) 397-8251		IRP-2-14-3015

* Attach Additional Sheets If Necessary

FEB 06 2014