

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
100 Rio Brazos Road, Aztec, NM 87410  
District IV  
100 S. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**RECEIVED**  
FEB 04 2014  
**NMOCD ARTESIA**

Form C-141  
Revised October 10, 2003  
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

**Release Notification and Corrective Action**

*WMP 1406539248* OPERATOR  Initial Report  Final Report

Name of Company	COG OPERATING LLC <i>229137</i>	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	SRO 17 State Com	Facility Type	Tank Battery
Surface Owner State	Mineral Owner	Lease No. (API#) 30-015-38257	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	09	26S	28E					Eddy
				Latitude 32.06168		Longitude 104.09991		

**NATURE OF RELEASE**

Type of Release Produced water	Volume of Release 15bbls	Volume Recovered 14bbls
Source of Release Poly line Y connection	Date and Hour of Occurrence 01-21-2014	Date and Hour of Discovery 01-21-2014 1:00pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

The connection on the Y failed due to moving the line a week earlier.

Describe Area Affected and Cleanup Action Taken.\*

Initially 15bbls of produced water were released. We were able to recover 14bbls of produced water with a vacuum truck. All free fluids have been recovered. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Robert Grubbs Jr.</i>		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Robert Grubbs Jr.		Approved by District Supervisor: <i>Heuban</i>	
Title: Senior Environmental Coordinator		Approval Date: <i>3/6/14</i>	Expiration Date:
E-mail Address: rgrubbs@concho.com		Conditions of Approval:	
Date: 02-03-2014	Phone: 432-661-6601	Remediation per OCD Rule & Guidelines, & <input type="checkbox"/> Attached	

\* Attach Additional Sheets If Necessary

Remediation per OCD Rule & Guidelines, &  Attached

PROPOSAL NO LATER THAN:


*4/6/14*

*ZRP 2183*

**Bratcher, Mike, EMNRD**

---

**From:** Robert Grubbs <RGrubbs@concho.com>  
**Sent:** Tuesday, February 04, 2014 3:08 PM  
**To:** Bratcher, Mike, EMNRD  
**Cc:** Robert McNeill; Production Mail  
**Subject:** C-141 Initial Report - SRO 17 State Com (TB)  
**Attachments:** 01-21-2014 SRO 17 State Com (SWD) Initial.pdf



*Mr. Bratcher,*

*Please see attached the C-141 Initial Report for a release that occurred at our SRO 17 State Com (TB) on 01-21-2014 in Eddy County New Mexico. We plan to assess the spill area timely.*

*Thank you,*

*Robert Grubbs Jr.  
Sr. Environmental Coordinator  
432.683.7443 (main)  
432.818.2369 (direct)  
432.661.6601 (cell)  
[rgrubbs@concho.com](mailto:rgrubbs@concho.com)  
Mailing Address:  
One Concho Center  
600 W. Illinois Avenue  
Midland, Texas 79701*



**CONFIDENTIALITY NOTICE:** *The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.*

**CONFIDENTIALITY NOTICE:** The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.