

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

nHMP1406926753

**OPERATOR**

Initial Report  Final Report

Name of Company: BOPCO, L.P. <u>260737</u>	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: Indian Flats Bass Federal Well#3	Facility Type: Exploration and Production
Surface Owner: Federal	Mineral Owner: Federal
API No. 30-015-21853	

**LOCATION OF RELEASE**


Unit Letter L	Section 35	Township 21S	Range 28E	Feet from the 1650	North/South Line South	Feet from the 330	East/West Line West	County: Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	--------------

Latitude N. 32.434079 Longitude W 104.064599

**NATURE OF RELEASE**

Type of Release: Crude oil and produced water	Volume of Release: 2 Bbl. Of crude oil and 8 Bbls of water	Volume Recovered: None
Source of Release: 3" poly flow line	Date and Hour of Occurrence: Date 1/24/14 Hour unknown	Date and Hour of Discovery: 1/24/14 at 11:00 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? Jim Amos with the BLM	
By Whom? Tony Savoie	Date and Hour 1/24/14 at 3:30 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

The 3" poly flow line split, the damaged area was cut out and the pipe was fused back together.

Describe Area Affected and Cleanup Action Taken.\*

The spill impacted an area measuring approximately 3200 sq.ft. on the well pad and adjacent drilling reserve pit. All of the fluid had soaked into the ground at the time of the site review.  
The spill will be remediated using the NMOCD recommended guidelines for the remediation of leaks.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Tony Savoie</u>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Tony Savoie	Approved by Environmental Specialist: <u>[Signature]</u>	
Title: Waste Management and Remediation Specialist	Approval Date: <u>3/10/14</u>	Expiration Date: <u>NA</u>
E-mail Address: <u>tasavoie@basspet.com</u>	Conditions of Approval: Remediation per OCD Rule & Guidelines, & like approval by BLM. <b>SUBMIT REMEDIATION</b>	Attached <input type="checkbox"/>
Date: <u>2/3/14</u> Phone: <u>432-556-8730</u>	<b>PROPOSAL NO LATER THAN:</b> <u>4/10/14</u>	

\* Attach Additional Sheets If Necessary

2RP 2191