


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised August 8, 2011

Submit Copy to Appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

*njw* 1402938083 OPERATOR  Initial Report  Final Report

Name of Company: Cimarex Energy Company <i>162683</i>	Contact: Johnny Titsworth
Address: 600 N. Marienfield, Suite 600, Midland, TX 79701	Telephone No. (432)250-2059
Facility Name: Amoco Federal #13	Facility Type: Well
Surface Owner: Federal	Mineral Owner:
API No: 30-015-25810	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	28	26	29	760	FNL	660	FEL	Eddy

Latitude: 32.01892 Longitude: -103.98275

**NATURE OF RELEASE**

Type of Release: Produced Water / Crude	Volume of Release: 11 BBLs	Volume Recovered: 1 BBL
Source of Release: Poly Flowline	Date & Hour of Occurrence: 1/10/14	Date & Hour of Discovery: 1/10/14
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Max Pfaff	
By Whom? Jose Corona	Date and Hour: 11:00 1/10/14	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
2" poly flow line that runs parallel to the lease road was run over, and was split open. The well was not running, but tubing & casing valves were open and fluid was released onto the road way.

Describe Area Affected and Cleanup Action Taken.\*  
The fluid filled a depression on the lease road & ran off the road into an erosional ravine, and traveled approximately 480 feet. Tetra Tech will assess the spill. Crude = 1 BBLs / 0 BBLs Produced Water = 10 BBLs / 1 BBLs

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Johnny Titsworth	Approved by Environmental Specialist: Signed By	
Title: Environmental Compliance Coordinator	Approval Date: <b>JAN 29 2014</b>	Expiration Date:
E-mail Address: jtitsworth@cimarex.com	Conditions of Approval: Remediation per OCD Rule & Guidelines, & like approval by BLM. <b>SUBMIT REMEDIATION PROPOSAL NO LATER THAN:</b>	Attached <input type="checkbox"/>
Date: 1/15/14 Phone: (432)-250-2059	<b>March 1, 2014</b>	<b>2RP-2168</b>

\* Attach Additional Sheets If Necessary

## Bratcher, Mike, EMNRD

---

**From:** Johnny Titsworth <jtitsworth@cimarex.com>  
**Sent:** Wednesday, January 15, 2014 8:52 AM  
**To:** 'jvancure@blm.gov'; Bratcher, Mike, EMNRD  
**Cc:** Christine Alderman; Max Pfaff; 'ike.tavarez@tetrattech.com'  
**Subject:** Amoco Federal #13  
**Attachments:** Amoco Fed 13.pdf

Jennifer / Mike

We had a spill on the Amoco Federal #13 on Friday 1/10/14. The spill was caused when someone ran over the flow line and split it. The spill pooled on the lease road and then ran approximately 480' in a ravine. We will assess the spill and send in a report. If you have any questions or concerns, feel free to contact us. Thanks.

**Johnny Titsworth**

***EHS - Environmental Compliance***

*600 N. Marienfeld St., Suite 600*

*Midland, TX 79701*

Mobile: 432-250-2059

Office: 432-620-1983

