


District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised August 8, 2011

Submit a copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NHMP1409224400

OPERATOR Initial Report Final Report

Name of Company	Burnett Oil Co., Inc. <i>3080</i>	Contact	Belton Mathews
Address	801 Cherry Street, Fort Worth, Texas 76102	Telephone No.	817-332-5108 X201
Facility Name	Gissler A 46	Facility Type	Well

Surface Owner	BLM	Mineral Owner	BLM	API No.	30-015-41544
---------------	-----	---------------	-----	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	23	17S	30E	330	North	330	East	Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Mix of Oil & Water	Volume of Release	Approx 25 bbls	Volume Recovered	20 bbls
Source of Release	Ruptured Flowline	Date and Hour of Occurrence	12/17/2013 6:00am	Date and Hour of Discovery	
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Belton Mathews	Date and Hour	12/17/2013 6:00am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
High line pressure caused line to rupture. Shut off well and replaced line.

Describe Area Affected and Cleanup Action Taken.*
Clean up plan attached.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Leslie Garvis</i>	OIL CONSERVATION DIVISION	
Printed Name: Leslie Garvis	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Regulatory Coordinantor	Approval Date: <i>4-2-14</i>	Expiration Date: <i>NA</i>
E-mail Address: lgarvis@burnettoil.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 1/28/14	Phone: 817-332-5108	

Remediation per OCD Rule & Guidelines. **SUBMIT REMEDIATION PROPOSAL NO LATER THAN:**
5-2-14

2RP-2241

* Attach Additional Sheets If Necessary

Bratcher, Mike, EMNRD

From: Leslie Garvis <lgarvis@burnettoil.com>
Sent: Tuesday, January 28, 2014 9:17 AM
To: Bratcher, Mike, EMNRD
Cc: Mike Burton; Belton Mathews; Shawna Matthews; Mark Jacoby
Subject: C 141 Release Reports
Attachments: GA2 Battey_2013.12.22.pdf; GA46_2013.12.17.pdf

Hi Mike,

Attached you will find the C-141 and documentation for both the Gissler A 2 Battery and the Gissler A 46 well.

I have a package going out to your office tonight so I will include the originals of both of these.

Please let me know if you have any questions or need any additional information. I will submit the Final report once the work has been completed.

Thank you

Leslie M. Garvis
Regulatory Coordinator
Burnett Oil Co., Inc.
Burnett Plaza-Suite E500
801 Cherry Street - Unit #9
Fort Worth, TX 76102
Office: 817.332.5108 ext 6326
Fax: 817.332.2438
Email: lgarvis@burnettoil.com

This message is intended only for the person(s) to which it is addressed and may contain privileged, confidential and/or insider information. If you have received this communication in error, please notify us immediately by replying to the message and deleting it from your computer. Any disclosure, copying, distribution, or the taking of any action concerning the contents of this message and any attachment(s) by anyone other than the named recipient(s) is strictly prohibited.

From: Patterson, Heather, EMNRD [<mailto:Heather.Patterson@state.nm.us>]
Sent: Friday, March 28, 2014 7:33 AM
To: Leslie Garvis
Cc: Bratcher, Mike, EMNRD
Subject: Spill report information

Ms. Garvis,

I am writing you in reference to a number of C-141 spill reports we have received from you, the Gissler A 46 (12/17/13), Jackson B-5 Gas Line (3/24/14), and the Gissler B 2 Battery (12/22/13). On all three of these reports you indicate both oil and produced water was spilled, but the volume of released fluid is not broken down. We need you to provide a detailed breakdown of both the released and recovered fluids, how much was oil and how much was produced water. This information is necessary for our records. Also, on the Gissler B 2 Battery spill report the volume of release is listed as "minimal spray". I will need an amount in order to process this report.

Thank you,

Heather Patterson
Environmental Specialist
NMOCD District II
(575)748-1283 ext.101

This message is intended only for the person(s) to which it is addressed and may contain privileged, confidential and/or insider information. If you have received this communication in error, please notify us immediately by replying to the message and deleting it from your computer. Any disclosure, copying, distribution, or the taking of any action concerning the contents of this message and any attachment(s) by anyone other than the named recipient(s) is strictly prohibited.

Patterson, Heather, EMNRD

From: Jacob Kamplain <jkamplain@rice-ecs.com>
Sent: Tuesday, April 01, 2014 10:25 AM
To: Patterson, Heather, EMNRD
Cc: hconder@rice-ecs.com; lgarvis@burnettoil.com; 'Laura Flores'; 'Shawna Matthews'
Subject: RE: Spill report information

Mrs. Patterson here is the break down for the 3 Burnett Oil site.

The Gissler A #46 (12/22/13) 20 bbls of water lost & 5 bbls oil lost, 16 bbls water recovered & 3 bbls oil recovered.

The Jackson B-5 Gasline (3/24/13) 5 bbls of water lost & 1 bbl of oil lost, 0 bbls water recovered and oil was burnt in fire.

The Gissler B-2 Battery 9/12/22/13) 3 bbls of water lost & 2 bbls of oil lost, 0 bbls water was recovered & 0 bbls oil was recovered.

Please feel free to contact me if you have any other questions or concerns. Thank you.

From: Laura Flores [<mailto:lflores@rice-ecs.com>]
Sent: Friday, March 28, 2014 7:55 AM
To: 'Hack Conder'
Cc: 'Jacob Kamplain'; 'Lara Weinheimer'
Subject: FW: Spill report information

From: Leslie Garvis [<mailto:lgarvis@burnettoil.com>]
Sent: Friday, March 28, 2014 7:48 AM
To: lflores@rice-ecs.com
Cc: Shawna Matthews
Subject: FW: Spill report information

Good Morning Laura,

I received this email from the OCD this morning requesting additional information. Can you please respond to their request?

Also – please copy me on anything that is filed with the OCD or BLM for Burnett Oil and any correspondence regarding any events in our field.

Thank you.

LESLIE M. GARVIS
REGULATORY COORDINATOR

BURNETT OIL Co., INC.
BURNETT PLAZA-SUITE 1500
801 CHERRY STREET - UNIT #9
FORT WORTH, TX 76102-6881
OFFICE: (817) 332-5108
FAX: (817) 332-2438
EMAIL: LGARVIS@BURNETTOIL.COM