

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
20 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003  
Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

*n HAP 1408436341*

<b>OPERATOR</b>		<input checked="" type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Name of Company	COG OPERATING LLC <i>229137</i>	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Bragg 10 Fee #001H	Facility Type	Tank Battery
Surface Owner	Private	Mineral Owner	
		Lease No. (API#) 30-015-41462	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	10	19S	26E					Eddy

Latitude 32.66828      Longitude 104.37720

**NATURE OF RELEASE**

Type of Release Oil	Volume of Release 55bbls	Volume Recovered 50bbls
Source of Release Sight glass on FWKO	Date and Hour of Occurrence 03-06-2014	Date and Hour of Discovery 03-06-2014 10:00am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD	
By Whom? Michelle Mullins	Date and Hour 03-07-2014 07:25am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

A sight glass failed on a FWKO at the top connection. Sight glass has been replaced.


Describe Area Affected and Cleanup Action Taken.\*

Initially 55bbls of oil released. We were able to recover 50bbls of oil with a vacuum truck. The spill was contained inside the lined facility. All free fluid has been recovered. Any contaminated gravel has been removed, the liner has been steam cleaned and we has replaced with fresh gravel as necessary. This location has been returned to its prior condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Robert Grubbs Jr.</i>		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Robert Grubbs Jr.	Approved by District Supervisor:		
Title: Senior Environmental Coordinator	Approval Date: <i>3/25/14</i>	Expiration Date: <i>NA</i>	
E-mail Address: rgrubbs@concho.com	Conditions of Approval: <i>Final</i>		Attached <input type="checkbox"/>
Date: 03-14-2014	Phone: 432-661-6601		

\* Attach Additional Sheets If Necessary




*2RP-2221*

**Bratcher, Mike, EMNRD**

---

**From:** Robert Grubbs <RGrubbs@concho.com>  
**Sent:** Friday, March 14, 2014 1:48 PM  
**To:** Bratcher, Mike, EMNRD  
**Cc:** Robert McNeill; Production Mail  
**Subject:** C-141 Initial / Final Report - Bragg 10 Fee #001 (TB)  
**Attachments:** 03-06-2014 Bragg 10 Fee #001H (TB) Initial - Final.pdf



*Mr. Bratcher,*

*Please see attached the C-141 Initial / Final Report for a release that occurred at our Bragg 10 Fee #001 (TB) on 03-06-2014 in Eddy County New Mexico. This is a lined facility.*

*Thank you,*

*Robert Grubbs Jr.  
Sr. Environmental Coordinator  
432.683.7443 (main)  
432.818.2369 (direct)  
432.661.6601 (cell)  
rgrubbs@concho.com  
Mailing Address:  
One Concho Center  
600 W. Illinois Avenue  
Midland, Texas 79701*



**CONFIDENTIALITY NOTICE:** *The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.*

**CONFIDENTIALITY NOTICE:** The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

## Bratcher, Mike, EMNRD

---

**From:** Michelle Mullins <MMullins@concho.com>  
**Sent:** Friday, March 07, 2014 6:25 AM  
**To:** Bratcher, Mike, EMNRD  
**Cc:** Robert Grubbs  
**Subject:** Bragg 10 Fee #1H-Immediate Notification

Mr. Bratcher:

At approximately 10:00 a.m. on 3/06/2014, a produced fluid release was discovered at the above-referenced facility. An estimated 55 barrels of produced fluid was released. The cause of the release is currently under investigation. We will follow up within 15 days with a C-141 Report. GPS coordinates, legal description and driving directions are listed below.

32.66828 104.37720

Bragg 10 Fee #1H  
Unit M Sec. 10  
T19S R26E  
150' FSL & 330' FWL  
Eddy County, NM  
API 30-015-41462

From Artesia, travel south on Highway 285 to CR-35 (Crane Road). Turn east and travel 1.5 miles to Lake Road. Turn north on Lake Road and travel .6 miles, turn west and travel .4 miles to location.

Thank you.

Michelle Mullins  
Environmental Coordinator  
COG Operating, LLC  
(432) 934-1052  
[mmullins@concho.com](mailto:mmullins@concho.com)

*CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.*

**CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.**