

RECEIVED

MAR 17 2014

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
10 Rio Brazos Road, Aztec, NM 87410
District IV
100 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NMOCD ARTESIA

Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

HP 1408449795

Name of Company		COG OPERATING LLC <i>229137</i>	Contact	Robert McNeill
Address		600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name		Down South State Com#001H	Facility Type	Tank Battery
Surface Owner	State	Mineral Owner	Lease No. (API#) 30-015-41442	

OPERATOR

Initial Report

Final Report

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	19	26S	28E					Eddy

Latitude 32.03328

Longitude 104.11920

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	115bbbls	Volume Recovered	113bbbls
Source of Release	3" collar on overflow water tank	Date and Hour of Occurrence	03-08-2014	Date and Hour of Discovery	03-08-2014 1:00pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher - NMOCD		
By Whom?	Michelle Mullins	Date and Hour	03-11-2014 04:01am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A 3" collar on the overflow water tank was inserted incorrectly and broke free. We installed a new collar and nipple on the water tank.

Describe Area Affected and Cleanup Action Taken.*

Initially 115bbbls of produced water were released. We were able to recover 113bbbls of produced water with a vacuum truck. The spill was contained inside the lined facility. All free fluid has been recovered. Any contaminated gravel has been removed, the liner has been steam cleaned and we has replaced with fresh gravel as necessary. This location has been returned to its prior condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases, which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:	<i>Robert Grubbs Jr.</i>	Approved by District Supervisor:		<i>[Signature]</i>	
Printed Name:	Robert Grubbs Jr.	Approval Date:	3-25-14	Expiration Date:	NA
Title:	Senior Environmental Coordinator	Conditions of Approval:		<i>Final</i>	
E-mail Address:	rgrubbs@concho.com	Attached		<input type="checkbox"/>	
Date:	03-17-2014	Phone:	432-661-6601		

* Attach Additional Sheets If Necessary

2RP-2223

Bratcher, Mike, EMNRD

From: Robert Grubbs <RGrubbs@concho.com>
Sent: Monday, March 17, 2014 1:01 PM
To: Bratcher, Mike, EMNRD
Cc: Robert McNeill; Production Mail
Subject: C-141's Initial/Final Reports - Myox 32 State #001H (TB) - Down South State Com #001H
Attachments: 03-08-2014 Down South State Com #001H (TB) Initial - Final.pdf; 03-07-2014 Myox 32 State #001H (TB) Initial - Final.pdf



Mr. Bratcher,

Please see attached the C-141's Initial/Final Reports for the releases that occurred at our Myox 32 State #001H (TB) on 03-07-2014 and our Down South State Com #001H on 03-08-2014 in Eddy County New Mexico. These are lined facility

Thank you,

*Robert Grubbs Jr.
Sr. Environmental Coordinator
432.683.7443 (main)
432.818.2369 (direct)
432.661.6601 (cell)
rgrubbs@concho.com
Mailing Address:
One Concho Center
600 W. Illinois Avenue
Midland, Texas 79701*



CONFIDENTIALITY NOTICE: *The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.*

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

Bratcher, Mike, EMNRD

From: Michelle Mullins <MMullins@concho.com>
Sent: Tuesday, March 11, 2014 6:01 AM
To: Bratcher, Mike, EMNRD
Cc: Robert Grubbs
Subject: Down South State Com #1H

Mr. Bratcher:

At approximately 1:00 p.m. on 3/08/2014, a produced fluid release was discovered at the above-referenced facility. An estimated 115 barrels of produced fluid was released. The cause of the release is currently under investigation. We will follow up within 15 days with a C-141 Report. GPS coordinates, legal description and driving directions are listed below.

32.03328 104.11920

Down South State Com #1H
Unit A Sec. 19
T26S R28E
660' FNL & 330' FEL
Eddy County, NM
API 30-015-41442

From Artesia, travel south on Highway 285 to White's City Road. Turn west and go approximately 3 miles. Turn south and go approximately 3 miles. Location is on the west side of lease road.

Michelle Mullins
Environmental Coordinator
COG Operating, LLC
(432) 934-1052
mmullins@concho.com

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.