

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
200 Rio Brazos Road, Aztec, NM 87410
District IV
20 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
MAR 27 2014
NMOCD ARTESIA

Form C-141
Revised October 10, 2003
Copies to appropriate
Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nHMP1409045328 OPERATOR Initial Report Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	SRO SWD #102	Facility Type	

Surface Owner State	Mineral Owner	Lease No. (API#)	30-015-21398
---------------------	---------------	------------------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	16	26S	28E					Eddy

Latitude 32.04430 Longitude 104.09031

NATURE OF RELEASE

Type of Release Produced water	Volume of Release 10bbls	Volume Recovered 0bbls (Thick Gravel)
Source of Release 3" Vic check valve	Date and Hour of Occurrence 03-20-2014	Date and Hour of Discovery 03-20-2014 09:00am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A 3" Vic check valve on discharge side of the produced water disposal pump. Replace the Vic check valve with a new one.

Describe Area Affected and Cleanup Action Taken.*

Initially 10bbls of produced water were released. We were able to recover 0bbls of produced water due to several inches of gravel. The spill was contained inside the lined facility. All free fluid has been recovered. Any contaminated gravel has been removed, the liner has been steam cleaned and we has replaced with fresh gravel as necessary. This location has been returned to its prior condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION


Signature:	Approved by District Supervisor:	
Printed Name: Robert Grubbs Jr.	Approval Date: 3-31-14	Expiration Date: 1/4
Title: Senior Environmental Coordinator	Conditions of Approval: Final	
E-mail Address: rgrubbs@concho.com	Attached <input type="checkbox"/>	
Date: 03-27-2014 Phone: 432-661-6601		

* Attach Additional Sheets If Necessary

2RP-2237

Bratcher, Mike, EMNRD

From: Robert Grubbs <RGrubbs@concho.com>
Sent: Thursday, March 27, 2014 1:40 PM
To: Bratcher, Mike, EMNRD
Cc: Robert McNeill; Production Mail
Subject: C-141 Initial/Final Report - SRO SWD #002 (SWD)
Attachments: 03-20-2014 SRO SWD #102 (SWD) Initial - Final.pdf



Mr. Bratcher,

Please see attached the C-141 Initial/Final Report for a release that occurred at our SRO SWD #002 (SWD) on 03-20-2014 in Eddy County New Mexico. This is a lined facility.

Thank you,

*Robert Grubbs Jr.
Sr. Environmental Coordinator
432.683.7443 (main)
432.818.2369 (direct)
432.661.6601 (cell)
rgrubbs@concho.com
Mailing Address:
One Concho Center
600 W. Illinois Avenue
Midland, Texas 79701*



CONFIDENTIALITY NOTICE: *The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.*

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that

any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.