

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nHMP1410125196

OPERATOR

Initial Report Final Report

Name of Company: BOPCO, L.P. <i>260737</i>	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU 420 Tank Battery	Facility Type: Exploration and Production

Surface Owner: USA	Mineral Owner: USA	API No. 30-015-39795
--------------------	--------------------	----------------------

LOCATION OF RELEASE


Unit Letter P	Section 28	Township 25S	Range 31E	Feet from the 700	North/South Line South	Feet from the 1300	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude N 32.096093 Longitude W 103.778400

NATURE OF RELEASE

Type of Release: Crude oil and produced water	Volume of Release: 5 bbls crude oil and 5 bbls produced water	Volume Recovered: 1 bbl crude oil
Source of Release: Heater-treater fire tube gasket	Date and Hour of Occurrence: 2/28/14 time unknown	Date and Hour of Discovery: 2/28/14 at approximately 9:00 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*
The gasket on the heater-treater fire tube failed. The production well was shut in and the gasket was replaced.

Describe Area Affected and Cleanup Action Taken.*
The spill affected approximately 3200 sq.ft. of caliche well pad around the process equipment earthen containment and approximately 4000 sq.ft. of pasture area was lightly misted.
The process equipment and vegetation were washed down with soap and water the day of the release. All of the free standing fluid was picked up with a vacuum truck.
The spill area will be cleaned up in accordance to the NMOCD and BLM remediation guidelines

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Waste Management and Remediation Specialist	Approval Date: <i>4/11/14</i>	Expiration Date:
E-mail Address: <i>tasavoie@basspet.com</i>	Conditions of Approval: Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	Attached <input type="checkbox"/>
Date: 3/7/14 Phone: 432-556-8730	<i>5/11/14</i>	<i>28P-2250</i>

* Attach Additional Sheets If Necessary