

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

*Revision*

**Release Notification and Corrective Action**

*nHMP1410140947*

<b>OPERATOR</b>		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company: Mewbourne Oil Company <i>14744</i>	Contact: Zack Thomas		
Address: PO Box 5270 Hobbs NM 88241	Telephone No. 575-393-5905		
Facility Name: Pine Box 17 AP Fed Com #1H	Facility Type: Producing Oil Well		
Surface Owner: Kevin Wilbanks	Mineral Owner: BLM	API No. 30-015-39545	

**LOCATION OF RELEASE**

Unit Letter A	Section 17	Township 20S	Range 25E	Feet from the 342'	North/South Line North	Feet from the 427'	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release: Oil(75 bbls)/produced water(15 bbls)	Volume of Release: 90 bbls	Volume Recovered: 75 bbls (65 Oil/10 w)
Source of Release: Oil Well	Date and Hour of Occurrence 3-27-14	Date and Hour of Discovery 3-27-14 9:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Kevin Wilbanks	
By Whom? Ricky Apperson	Date and Hour 3-27-14 9:30 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

**RECEIVED**  
 APR 07 2014  
**NMOCD ARTESIA**

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
 Bottom sight glass on the heater treater broke (cause unknown) and drained the vessel. When pumper arrived on location valves to sight glass were closed stopping the release.

Describe Area Affected and Cleanup Action Taken.\*  
 Affected area- Inside the containment(standing fluid). 75 ft on pad surface north of separation equipment(standing fluid), 125 ft east of separation equipment onto reclaimed area (overspray). Separation equipment will be cleaned with power washer and contaminated soil on pad and reclaimed area will be removed and hauled off by Alfredo's trucking and backhoe services.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Zack Thomas	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Environmental Rep.	Approval Date: <i>4/11/14</i>	Expiration Date: <i>NA</i>
E-mail Address: zthomas@mewbourne.com	Conditions of Approval: Remediation per OCD Rule & Guidelines. <b>SUBMIT REMEDIATION PROPOSAL NO LATER THAN:</b>	Attached <input type="checkbox"/>
Date: 3-28-14 Phone: 575-602-2188	<i>5/11/14</i>	

\* Attach Additional Sheets If Necessary

*2RP-2253*

## Bratcher, Mike, EMNRD

---

**From:** Zack Thomas <zthomas@mewbourne.com>  
**Sent:** Friday, March 28, 2014 9:59 AM  
**To:** jamos@blm.gov; Bratcher, Mike, EMNRD; Scott Lacy  
**Subject:** Pine Box 17 AP Fed Com #1H --C141  
**Attachments:** C141- Pine Box 17 AP Fed Com #1H.doc; pic19668.gif

(See attached file: C141- Pine Box 17 AP Fed Com #1H.doc)

(Embedded image Zack Thomas  
moved to file: Environmental Rep.  
pic19668.gif) Mewbourne Oil Company

Phone: (575)-602-2188  
Email: [ZThomas@Mewbourne.com](mailto:ZThomas@Mewbourne.com)  
701 S. Cecil  
Hobbs, NM 88240 US

## **Patterson, Heather, EMNRD**

---

**From:** Patterson, Heather, EMNRD  
**Sent:** Monday, April 07, 2014 9:57 AM  
**To:** 'zthomas@mewbourne.com'  
**Cc:** Bratcher, Mike, EMNRD  
**Subject:** Pine Box 17 Spill Report

<b>Tracking:</b>	<b>Recipient</b>	<b>Delivery</b>
	'zthomas@mewbourne.com'	
	Bratcher, Mike, EMNRD	Delivered: 4/7/2014 9:57 AM

Mr. Thomas,

I am writing you in reference to the C-141 spill report we received for the Pine Box 17 AP Federal #001H (API 30-015-39545) release that occurred on March 27<sup>th</sup>. The report we received indicated 90bbbls of fluid released and 75bbbls of fluid recovered, and in the body of the report that fluid is listed as both crude oil and produced water. We need you to provide a detailed breakdown of both the released and recovered fluids, how much was oil and how much was produced water. This information is necessary for our records.

Thank you,

Heather Patterson  
Environmental Specialist  
NMOCD District II  
(575)748-1283 ext.101

## Patterson, Heather, EMNRD

---

**From:** Zack Thomas <zthomas@mewbourne.com>  
**Sent:** Monday, April 07, 2014 12:38 PM  
**To:** Patterson, Heather, EMNRD  
**Subject:** Fwd: Revised Pine Box 17 AP-- C141  
**Attachments:** C141- Pine Box 17 AP Fed Com #1H.doc; ATT00001.htm

Sent from my iPhone

Begin forwarded message:

**From:** "Zack Thomas" <[zthomas@mewbourne.com](mailto:zthomas@mewbourne.com)>  
**Date:** April 4, 2014 at 2:15:37 PM MDT  
**To:** [dwhitloc@blm.gov](mailto:dwhitloc@blm.gov)  
**Subject:** Revised Pine Box 17 AP-- C141