

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

| | | | |
|-----------------|---|---------------|----------------|
| Name of Company | COG Operating LLC | Contact | Pat Ellis |
| Address | 600 W. Illinois Avenue, Midland, TX 79701 | Telephone No. | (432) 230-0077 |
| Facility Name | Choctaw State #001 | Facility Type | Tank Battery |

| | | |
|----------------------|---------------|---|
| Surface Owner: State | Mineral Owner | Lease No. (API#) 30-015- 22815 |
|----------------------|---------------|---|

LOCATION OF RELEASE

24011

| | | | | | | | | |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
| A | 16 | 17S | 31E | | | | | Eddy |

Latitude N 32.51975° Longitude W 104.37667°

NATURE OF RELEASE

| | | |
|--|--|---|
| Type of Release: Oil and Produced Water | Volume of Release 5 bbls Oil 20 bbls Produced Water | Volume Recovered 5 bbls Oil 18 bbls Produced Water |
| Source of Release: Love-joy coupling on water transfer pump. | Date and Hour of Occurrence 02/26/2013 | Date and Hour of Discovery 02/26/2013 5:00 a.m. |
| Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? Mike Bratcher—OCD | |
| By Whom? Michelle Mullins | Date and Hour 02/26/2013 10:02 a.m. | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. N/A | |

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The Love-joy coupling broke on the water transfer pump. The coupling has been replaced.

Describe Area Affected and Cleanup Action Taken.*

Tetra Tech personnel inspected the site and collected samples to define the spills extent. Soil that exceeded RRAL was removed and hauled away for proper disposal. The site was then brought up to surface grade with clean backfill material. Tetra Tech prepared a closure report and submitted it to NMOCD for review.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | |
|---|----------------------------------|-----------------------------------|
| Signature: | OIL CONSERVATION DIVISION | |
| Printed Name: Ike Tavarez | Approved by District Supervisor: | |
| Title: Project Manager | Approval Date: 4/24/14 | Expiration Date: NA |
| E-mail Address: Ike.Tavarez@TetraTech.com | Conditions of Approval: Final | Attached <input type="checkbox"/> |
| Date: 7-12-13 Phone: (432) 682-4559 | | |

* Attach Additional Sheets If Necessary

2RP-1581