

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OCD

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

HOBBS OCD

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

MAY 08 2014

MAY 08 2014

RECEIVED

RECEIVED

Release Notification and Corrective Action

OPERATOR

Initial Report  Final Report

Name of Company	Celero Energy II, LP	Contact	Bruce Woodard
Address	400 W. Illinois Ave, Ste 160 Midland, Texas 79701	Telephone No.	(432) 686-1883
Facility Name	Priest #1 Abandoned Tank Battery	Facility Type	Former Tank Battery

Surface Owner: Private	Mineral Owner	Lease No. (API#)	30-025-09865
------------------------	---------------	------------------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	1	15S	37E					Lea

Latitude 33.04994° N Longitude 103.15944° W

NATURE OF RELEASE

Type of Release: Reclamation	Volume of Release Not applicable	Volume Recovered Not applicable
Source of Release: Not applicable	Date and Hour of Occurrence Not applicable	Date and Hour of Discovery Not applicable
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? Geoffrey Leking - NMOCD	
By Whom? Not applicable	Date and Hour Not applicable	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. Not applicable	


If a Watercourse was Impacted, Describe Fully.\*  
Not applicable.

DTW = 55'

Describe Cause of Problem and Remedial Action Taken.\*  
Celero voluntarily decided to dismantle and reclaimed the abandoned tank battery. Tetra Tech evaluated the soils at the abandoned tank battery and submitted a work plan to the NMOCD for approval.

Describe Area Affected and Cleanup Action Taken.\*  
Based on the evaluation, Tetra Tech prepared a work plan and submitted to the NMOCD for review and approval. The remediation and reclamation was implemented in accordance to the approved work plan. Tetra Tech prepared closure report detailing the all of the remediation and closure activities and submitted the report to the NMOCD for review.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION  Environmental Specialist	
Printed Name: Bruce Woodard	Approved by District Supervisor	
Title: VP Operations	Approval Date: 5/8/14	Expiration Date: —
E-mail Address: bwoodard@celeroenergy.com	Conditions of Approval: —	Attached <input type="checkbox"/>
Date: 5/7/14 Phone: (432) 686-1883		IRP-05-14-3036

\* Attach Additional Sheets If Necessary

h