


REVISED

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Copies to appropriate
office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

HMP 1413235805

OPERATOR

Initial Report Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Chase Settle
Address 104 S. 4 TH Street	API Number 30-015-26950	Telephone No. 575-748-4171
Facility Name Mimosa Federal SWD #4		Facility Type Battery

Surface Owner Federal	Mineral Owner Federal	Lease No. NM-36935
--------------------------	--------------------------	-----------------------

LOCATION OF RELEASE

Unit Letter N	Section 4	Township 20S	Range 24E	Feet from the 660'	North/South Line South	Feet from the 1980'	East/West Line West	County Eddy
------------------	--------------	-----------------	--------------	-----------------------	---------------------------	------------------------	------------------------	----------------

Latitude 32.59735 Longitude 104.59513

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 35 B/PW	Volume Recovered 15 B/PW
Source of Release Broken water leg	Date and Hour of Occurrence 4/28/2014; 9:00 AM	Date and Hour of Discovery 4/28/2014; 9:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/NMOC D II	
By Whom? Robert Asher/Yates Petroleum Corporation	Date and Hour 4/29/2014; AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		

Describe Cause of Problem, and Remedial Action Taken.*
Water leg on tank broke due to wind.

Describe Area Affected and Cleanup Action Taken.*
An approximate area of 169' X 64' was impacted within the bermed battery. The valve was shut off and vacuum trucks were called to clean up the spill. Impacted soils will be excavated and hauled to a NMOCD approved facility. **Depth to Ground Water: >100' (approximately 360', Section 4, T20S-R24E, per NMOSE), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:

Printed Name: Chase Settle

Title: Environmental Regulatory Agent

E-mail Address: CSettle@yatespetroleum.com

Date: Tuesday, May 06, 2014 Phone: 575-748-4171

OIL CONSERVATION DIVISION

Approved by District Supervisor:

Approval Date: 5/12/14 Expiration Date: NA

Conditions of Approval: Remediation per OCD Rule & Guidelines, & like approval by BLM. **SUBMIT REMEDIATION PROPOSAL NO LATER THAN:**

Attached

* Attach Additional Sheets If Necessary

6/12/14
2RP-2292

Bratcher, Mike, EMNRD

From: Tanna Adams <TCAAdams@yatespetroleum.com>
Sent: Tuesday, May 06, 2014 3:30 PM
To: Bratcher, Mike, EMNRD
Cc: Chase Settle; Bob Asher
Subject: Revised Mimosa Federal SWD #4 C-141
Attachments: Mimosa Federal.pdf

Mr. Bratcher,

Here is the revised C-141 for the Mimosa Federal SWD #4.

Thank you,

Tanna Adams

Yates Petroleum Corporation
Environmental Tech
Environmental Department
TCAAdams@yatespetroleum.com

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.

Bratcher, Mike, EMNRD

From: Bob Asher <BobA@yatespetroleum.com>
Sent: Tuesday, April 29, 2014 12:18 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Dade, Randy, EMNRD; dwhitloc@blm.gov; jamos@blm.gov
Cc: Amber Cannon; Chase Settle; Katie Parker; Manuel Gonzalez; Tanna Adams
Subject: Release Notification (Mimosa Federal SWD #4)

Yates Petroleum Corporation is reporting a release at the following location (4/28/2014; approximately 11:30 AM).

Mimosa Federal SWD #4
30-015-26950
Section 4, T20S-R24E
660 FSL & 1980 FWL
Eddy County, New Mexico

Released: 30 B/PW; Recovered: Unknown at this time.

Release caused not known at this time. Vacuum truck(s) were called.

A Form C-141 Initial Report will be submitted with complete information.

Thank you.

Robert Asher
NM Environmental Regulatory Supervisor
Yates Petroleum Corporation
105 S. 4th Street
Artesia, NM 88210
575-748-4217 (Office)
575-365-4021 (Cell)

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.
