


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

nHMP1413435475

OPERATOR

Initial Report Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 TH Street	API Number 30-015-37942	Telephone No. 575-748-1471
Facility Name Chamaeleon BIN State Com #1-H	Facility Type Battery	

Surface Owner State	Mineral Owner State	Lease No. V-7653, V-7639, VO-7654
------------------------	------------------------	--------------------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	25	26S	27E	200'	North	1780'	East	Eddy

Latitude 32.01979 Longitude 104.14041

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 500 B/PW	Volume Recovered 480 B/PW
Source of Release Water transfer pump	Date and Hour of Occurrence 4/29/2014; AM	Date and Hour of Discovery 4/29/2014; AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/NMOCD II	
By Whom? Robert Asher/Yates Petroleum Corporation	Date and Hour 4/30/2014; AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Poly line from the discharge pump ruptured. Vacuum truck(s), roustabout and backhoe crew called.		
Describe Area Affected and Cleanup Action Taken.* An approximate area of 20' X 60' and 100' X 8' (partial released water was contained in lined/borned battery), 50' X 200' (partial released area outside of battery). Water discharge poly line ruptured, valves were shut and vacuum trucks were called to vacuum up the spill, roustabout crew called to repair line, backhoe crew called to scrap up impacted soils on pad area (impacted soils taken to an NMOCD approved facility. Further excavation work to be conducted impacted soils will be taken to an NMOCD approved facility. Vertical and horizontal delineation samples outside of battery will be taken and analysis ran for TPH & BTEX (chlorides for documentation). If initial analytical results for TPH & BTEX are under RRAL's a Final Report, C-141 will be submitted to the NMOCD requesting closure. If the analytical results are above the RRAL a work plan will be submitted to the NMOCD. Depth to Ground Water: <50' (approximately 25', per the Chevron/Texaco Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 20.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Robert Asher	Approved by District Supervisor:	
Title: NM Environmental Regulatory Supervisor	Approval Date: <u>5/14/14</u>	Expiration Date: <u>NA</u>
E-mail Address: boba@yatespetroleum.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: Tuesday, May 13, 2014 Phone: 575-748-4217	Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO LATER THAN:

6/14/14

2RP-2303

Bratcher, Mike, EMNRD

From: Tanna Adams <TCAAdams@yatespetroleum.com>
Sent: Tuesday, May 13, 2014 3:52 PM
To: Bratcher, Mike, EMNRD
Cc: Bob Asher
Subject: Chamaeleon BIN State Com #1-H C-141
Attachments: Chamaeleon.pdf

Mr. Bratcher,

Attached is the C-141 for the Chamaeleon BIN State Com #1-H.

Thank you,

Tanna Adams

Yates Petroleum Corporation

Environmental Tech

Environmental Department

TCAAdams@yatespetroleum.com

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.
