

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: BOPCO, L.P.	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: Poker Lake Unit #211	Facility Type: Exploration and Production
Surface Owner: Federal	Mineral Owner: Federal
API No. 30-015-33858	


LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	18	24S	30E	1980	South	1980	East	Eddy

Latitude 32.215792 Longitude 103.918552

NATURE OF RELEASE

Type of Release: Produced Water and Crude Oil	Volume of Release 10 bbls crude oil and 15 bbls produced water	Volume Recovered: 5 bbls total fluid
Source of Release: Pumping well stuffing box packing	Date and Hour of Occurrence 7/15/12 Time Unknown	Date and Hour of Discovery 7/15/12 Approximately 12:45 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD Emergency #104 and Jim Amos "BLM"	
By Whom? Tony Savoie	Date and Hour: 7/16/12 at 9:05 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* The well was shut in and the stuffing box packing was replaced.		



Describe Area Affected and Cleanup Action Taken.*
Approximately 8925 sq. ft. of caliche well pad and approximately 840 sq. ft. of pasture was affected by the release, a vacuum truck was used to pick up the free standing fluid and a backhoe was used to scrape up the heavily saturated soil on the well pad, the material was stockpiled on-site. The remediation will follow the NMOCD and BLM spill Guidelines.

Approximately 1,120 cu. yds of impacted soil was excavated from an area measuring approximately 10' to 40' in width, 220' in length, and 1' to 2' in depth. Impacted soil was hauled to an NMOCD-approved disposal facility. Confirmation soil samples were collected on approximate 50' intervals and submitted for laboratory analysis. **Please reference the attached Remediation Summary and Site Closure Request for detail of Remediation Activities.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Waste Management and Remediation Specialist	Approval Date: <i>5/15/14</i>	Expiration Date: <i>NA</i>
E-mail Address: <i>tasavoie@basspet.com</i>	Conditions of Approval: <i>Final</i>	Attached <input type="checkbox"/>
Date: <i>5/19/14</i>	Phone: 432-556-8730	

* Attach Additional Sheets If Necessary

2RP-1232