

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis
Santa Fe, NM 87505

RECEIVED
MAR 05 2014
NMOCD ARTESIA

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	COG Operating LLC	Contact	Pat Ellis
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	(432) 230-0077
Facility Name	Loco Hills Water System	Facility Type	6" Main Line
Surface Owner: Federal	Mineral Owner	Lease No. (API#)30-015-30032 Western Federal #1 Closest Well	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	30	17S	29E					Eddy

Latitude N32 48.514° Longitude W104. 06.509°

NATURE OF RELEASE



Type of Release: Produced Water / Skim Oil	Volume of Release 275 bbls	Volume Recovered 260 bbls
Source of Release: 6" Main Line	Date and Hour of Occurrence 6/22/2012	Date and Hour of Discovery 6/22/2012 10:30 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Batcher-OCD Jim Amos-BLM Terry Gregston-BLM	
By Whom? Michelle Mullins	Date and Hour 6/22/2012 4:43 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
A weld failed at the 4" poly swedge on the 6" main line causing a release of fluids. The swedge has been repaired and the line has been returned to service.

Describe Area Affected and Cleanup Action Taken.*
Tetra Tech personnel inspected the site and collected samples to define the spill extents. Soil that exceeded the RRAL was removed and hauled away for proper disposal. The site was then brought up to surface grade with clean backfill material. Tetra Tech prepared a closure report and submitted it to NMOCD for review.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Ike Tavarez (agent for COG)	Approved by District Supervisor: 	
Title: Project Manager	Approval Date: 5/20/14	Expiration Date: NA
E-mail Address: Ike Tavarez@tetrattech.com	Conditions of Approval: Final	Attached <input type="checkbox"/>
Date: 5-17-14 Phone: (432) 682-4559		

* Attach Additional Sheets If Necessary

2RP-1211