

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OCD
MAY 27 2014
RECEIVED

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Devon Energy	Contact Tracy Kidd
Address PO Box 250 Artesia, NM 88211	Telephone No. 575-513-0628
Facility Name Cotton Draw 32 State Fed Com 1H	Facility Type Oil
Surface Owner Federal	Mineral Owner State
API No. 30-025-40583	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	32	24S	32E	2310	South	660	East	Lea

Latitude: 32.1730272 N

Longitude: 103.6902696 W

NATURE OF RELEASE

Type of Release Spill Produced Water	Volume of Release 205BBLs	Volume Recovered 205BBLs
Source of Release Water transfer pump malfunction, tank overflow	Date and Hour of Occurrence May 22, 2014 7:50 AM	Date and Hour of Discovery May 22, 2014 7:50 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos/ BLM & Geoff Lecking/ OCD	
By Whom? Rebecca Jamison; Lease Operator.	Date and Hour 5/23/2014	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.* **Depth to g H₂O > 100'**

Describe Cause of Problem and Remedial Action Taken.*
Water transfer pump went down causing the water tank to run over. Issues regarding notification system are being troubleshot as pumper did not receive alerts when the pump malfunctioned. Tanks and containment will be steamed.

Describe Area Affected and Cleanup Action Taken.*
205 BBLs produced water were spilled into the lined containment. RW Trucking recovered all the water from containment.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Sandra Farley	OIL CONSERVATION DIVISION	
Printed Name: Sandra Farley		
Title: Field Admin Support	Approval Date: 05-22-2014	Expiration Date: 07-28-2014
E-mail Address: Sandy.Farley@dvn.com	Conditions of Approval: Site samples required. Debris & remediate	Attached <input type="checkbox"/>
Date: _____ Phone: 575.746.5587	IRP-05-14-3049 og-rid - 6132	

* Attach Additional Sheets If Necessary

**Site as per NMOCD guidelines.
Submit final C-14- by
07-28-2014**

MAY 27 2014