

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company BOPCO, L.P.	Contact: Tony Savoie
Address 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 432-556-8730
Facility Name Poker Lake Unit #114	Facility Type: <u>Exploration & Production</u>
Surface Owner: State of New Mexico	Mineral Owner State of New Mexico
API No. 30-015-28102	


LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	36	24S	30E	North	1982	West	2019	Eddy

Latitude ~~32.86647~~ ^{32.176120} Longitude ~~103.85771~~ ^{103.836300}

NATURE OF RELEASE

Type of Release: Produced water and crude oil	Volume of Release 10 bbls	Volume Recovered 0
Source of Release Well Head	Date and Hour of Occurrence 3/27/12 Time unknown	Date and Hour of Discovery 3/27/12 2:00 PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	



If a Watercourse was Impacted, Describe Fully.*
NA

Describe Cause of Problem and Remedial Action Taken.*
A 1/2" valve on the wellhead was accidentally opened, the valve handle was removed and the valve was plugged.

Describe Area Affected and Cleanup Action Taken.*
Spill affected area approximately 4800 sq. ft. on the caliche well pad. The impacted soil was scraped up and stockpiled on site. The spill was delineated by Diversified Field Services, Inc. Samples were submitted to a commercial lab for analyses. Impacted soils were removed to a NMOCD approved disposal facility. A liner was installed. The excavation was backfilled and the site was contoured to the surrounding landscape.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Tony Savoie	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Waste Mgmt. and Remediation Specialist	Approval Date: <u>5/22/14</u>	Expiration Date: <u>NA</u>
E-mail Address: TASavoie@BassPet.com	Conditions of Approval: <u>Final</u>	Attached <input type="checkbox"/>
Date: 12/12/13	Phone: 432-556-8730	

* Attach Additional Sheets If Necessary

2EP-1100