

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

HOBBS OCD

Form C-141  
Revised August 8, 2011

MAY 29 2014  
Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

### Release Notification and Corrective Action

#### OPERATOR

Initial Report  Final Report

Name of Company <b>Devon Energy</b>	Contact <b>Tracy Kidd</b>
Address <b>PO Box 250 Artesia, NM 88211</b>	Telephone No. <b>575- 513-0628</b>
Facility Name <b>Cotton Draw 32 State Fed Com 1H</b>	Facility Type <b>Oil</b>
Surface Owner <b>Federal</b>	Mineral Owner <b>State</b>
API No. <b>30-025-40583</b>	

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<b>I</b>	<b>32</b>	<b>24S</b>	<b>32E</b>	<b>2310</b>	<b>South</b>	<b>660</b>	<b>East</b>	<b>Lea</b>

Latitude: 32.1730272 N

Longitude: 103.6902696 W

#### NATURE OF RELEASE

Type of Release Spill <b>Produced Water</b>	Volume of Release <b>205BBLs</b>	Volume Recovered <b>205BBLs</b>
Source of Release <b>Water transfer pump malfunction, tank overflow</b>	Date and Hour of Occurrence <b>May 22, 2014 7:50 AM</b>	Date and Hour of Discovery <b>May 22, 2014 7:50 AM</b>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>Jim Amos/ BLM &amp; Geoff Lecking/ OCD</b>	
By Whom? <b>Rebecca Jamison; Lease Operator</b>	Date and Hour <b>5/23/2014</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Water transfer pump went down causing the water tank to run over. Issues regarding notification system are being troubleshot as pumper did not receive alerts when the pump malfunctioned. Tanks and containment will be steamed.

area 28' x 160'

Depth to gH<sub>2</sub>O 7100'

Describe Area Affected and Cleanup Action Taken.\*

205 BBLs produced water were spilled into the lined containment. RW Trucking recovered all the water from containment.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <b>Sandra Farley</b>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>Sandra Farley</b>	Approved by Environmental Specialist:	
Title: <b>Field Admin Support</b>	Approval Date: <b>05-29-14</b>	Expiration Date: <b>7-29-14</b>
E-mail Address: <b>Sandy.Farley@dvn.com</b>	Conditions of Approval: <b>Site Samples required. Debrute &amp; remediate</b>	Attached <input type="checkbox"/>
Date: _____ Phone: <b>575.746.5587</b>	<b>IRP-05-14-3083</b>	

\* Attach Additional Sheets If Necessary

the area as per NMOCD guides.  
Submit final C-141 by 7-29-14

07/04 6172

MAY 29 2014